



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Black
Year of manufacture	2013
Top speed	119 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	208 g/km
CO2 label	K





Internet history

Entry 2

Date	2021-09-27
Pictures	17
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-09-26
Pictures	2
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-11
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	14
Total items failed	3

MOT #10	2023-09-12 13:44
MOT test number	164868578931
Result	✓ Passed
Next expiry date	2024-09-11
Advice	Rear Exhaust mounting defective corroded (6.1.2 (a))
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing worn (5.2.3 (d) (ii))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #9** 2023-09-08 11:55**MOT test number** 967547178963**Result** ✗ Failed**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing worn (5.2.3 (d) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Exhaust mounting defective corroded (6.1.2 (a))**MOT #8** 2022-09-06 11:22**MOT test number** 567514775784**Result** ✓ Passed**MOT #7** 2021-09-11 07:56**MOT test number** 851429445046**Result** ✓ Passed**Advice** Central Front slight oil leak but not excessive**MOT #6** 2020-09-02 15:39**MOT test number** 389223211834**Result** ✓ Passed

**MOT #5** 2020-09-02 09:06**MOT test number** 615581952680**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Reversing lamp inoperative (4.6.1 (a))**MOT #4** 2019-05-23 08:48**MOT test number** 269862894914**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #3** 2018-05-23 12:33**MOT test number** 343421219742**Result** ✓ Passed**MOT #2** 2017-05-12 09:59**MOT test number** 903439871460**Result** ✓ Passed**MOT #1** 2016-05-23 10:40**MOT test number** 582731653978**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
11 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	11 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>LA62SMU</b>
Plate since	2019-06-29
Current registration	<b>LA62SMU</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-01-18
Last registration	2023-09-12
Complete history	<a href="#">See info</a>



Registration #1	2013-01-18	10 mi
Registration #2	2016-05-23	24.154 mi
Registration #3	2017-05-12	32.047 mi
Registration #4	2018-05-23	40.855 mi
Registration #5	2019-05-23	50.930 mi
Registration #6	2020-09-02	59.906 mi
Registration #7	2020-09-02	59.906 mi
Registration #8	2020-09-02	59.906 mi
Registration #9	2020-09-02	59.906 mi
Registration #10	2020-09-02	59.906 mi
Registration #11	2020-09-02	59.906 mi
Registration #12	2020-09-02	59.906 mi
Registration #13	2020-09-02	59.906 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	227236K