



CITROËN




report date: 2024-03-28

## General information

|                     |                  |
|---------------------|------------------|
| Make                | CITROEN          |
| Model               | C4 BLUEHDI FLAIR |
| Colour              | Blue             |
| Year of manufacture | 2015             |
| Top speed           | 114 mph          |
| 0 - 60 mph          | 10.7 seconds     |
| Gearbox             | 5 speed Manual   |

## Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 98 BHP              |
| Max. torque             | 254 Nm at 1.750 rpm |
| Engine capacity         | 1.560 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 74.3 mpg            |
| Consumption extra urban | 88.3 mpg            |
| Consumption combined    | 83.1 mpg            |
| CO2 emission            | 92 g/km             |
| CO2 label               | A                   |





## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-03-18 |
| MOT pass rate      | 67 %       |
| MOT passed         | 6          |
| Failed MOT tests   | 3          |
| Total advice items | 8          |
| Total items failed | 10         |

|                  |   |
|------------------|---|
| MOT #9           | 2024-03-19 16:43  |
| MOT test number  | 229019966934  |
| Result           | ✓ Passed  |
| Next expiry date | 2025-03-18  |
| Advice           | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |
| Advice           | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

|                         |   |
|-------------------------|---|
| MOT #8                  | 2024-03-19 16:43  |
| MOT test number         | 883517416148  |
| Result                  | ✗ Failed  |
| Pass with rectification | Nearside Front Headlamp missing (4.1.1 (a) (ii))                      |
| Advice                  | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |
| Pass with rectification | Front Windscreen washer provides insufficient washer liquid (3.5 (a)) |
| Advice                  | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

|                 |   |
|-----------------|---|
| MOT #7          | 2023-03-10 19:26  |
| MOT test number | 933578132742  |
| Result          | ✓ Passed  |
| Advice          | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) |

**MOT #6** 2023-03-10 18:08**MOT test number** 236591743165**Result** ✗ Failed**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Offside Rear Parking brake lever defective so that it cannot be satisfactorily operated (1.1.6 (d))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #5** 2023-03-07 08:38**MOT test number** 199676925408**Result** ✗ Failed**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords Several cuts on inner sidewall (5.2.3 (d) (i))**Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #4** 2022-02-26 14:45**MOT test number** 150590114303**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2021-03-09 14:17**MOT test number** 598894031674**Result** ✓ Passed



|                 |                  |
|-----------------|------------------|
| MOT #2          | 2019-06-04 13:28 |
| MOT test number | 886004897648     |
| Result          | ✓ Passed         |

|                 |                  |
|-----------------|------------------|
| MOT #1          | 2018-06-12 13:34 |
| MOT test number | 128437068225     |
| Result          | ✓ Passed         |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
18 March 2025

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 March             |
| <b>Days left</b>        | 305                             |
| <b>MOT expiry date</b>  | 18 March 2025                   |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |                |
|--|----------------|
| <b>Vehicle class</b>                           | 49             |
| <b>Band</b>                                    | A              |
| <b>Single payment (12 months)</b>              | £ 0,00,-       |
| <b>Single six month payment</b>                | Not applicable |
| <b>Total payable by 12 monthly instalments</b> | Not applicable |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 15,200 |
| Auction value               | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

|                      |               |
|----------------------|---------------|
| Number of plates     | 1             |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2024-03-28    |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2024-03-28    |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

|                   |             |
|-------------------|-------------|
| Finance company   | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type    | XXXXXXXX XX |
| Agreement term    | XXXXXXXX XX |
| Agreement number  | XXXXXXXX XX |
| Contact info      | XXXXXXXX XX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 10                       |
| First mileage registration | 2015-06-26               |
| Last registration          | 2024-03-19               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2015-06-26 | 27 mi     |
| Registration #2  | 2018-06-12 | 36.470 mi |
| Registration #3  | 2019-06-04 | 54.180 mi |
| Registration #4  | 2021-03-09 | 69.218 mi |
| Registration #5  | 2022-02-26 | 79.957 mi |
| Registration #6  | 2023-03-20 | 91.277 mi |
| Registration #7  | 2023-03-20 | 91.277 mi |
| Registration #8  | 2023-03-20 | 91.277 mi |
| Registration #9  | 2023-03-20 | 91.277 mi |
| Registration #10 | 2024-03-19 | 91.277 mi |

More info >



Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 90%                             |
| Children       | 85%                             |
| Pedestrian     | 43%                             |
| Safety systems | 97%                             |
| Overall rating | 80%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1729 mm |
| Height              | 1480 mm |
| Length              | 4157 mm |
| Wheel base          | 2595 mm |
| Kerb weight         | 1070 kg |
| Max. allowed weight | 1610 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 45 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |
| Number of axles    | 2                |
| Engine number      | JBHA3020802      |