



report date: 2024-03-29

General information

Make	LEXUS
Model	IS 300H SPORT
Colour	Black
Year of manufacture	2015
Top speed	125 mph
0 - 60 mph	8.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	220 BHP
Max. torque	520 Nm at 4.200 rpm
Engine capacity	2.494 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption combined	61.4 mpg
CO2 emission	107 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-09-23
Pictures	0
Listing price	View report

source: heycar.co.uk

**MOT history**

MOT expiry date	2024-09-21
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	5
Total items failed	6

MOT #8	2023-09-19 14:19
MOT test number	477929104504
Result	✓ Passed
Next expiry date	2024-09-21

MOT #7	2023-09-18 11:51
MOT test number	645643766508
Result	✗ Failed
Fail	Nearside Front Tyre has ply or cords exposed tread and sidewall 225/40r18 92y (5.2.3 (d) (ii))
Fail	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
Fail	Nearside Rear Tyre has ply or cords exposed tread and sidewall 25535r1894w (5.2.3 (d) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge badly worn on inner edge (5.2.3 (e))

MOT #6	2022-09-10 09:19
MOT test number	796844774183
Result	✓ Passed

MOT #5	2021-09-22 15:26
MOT test number	268327099062
Result	✓ Passed

**MOT #4** 2020-11-30 12:15**MOT test number** 836313768191**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))**MOT #3** 2019-11-21 15:24**MOT test number** 241885382980**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #2** 2018-12-18 11:23**MOT test number** 898769224380**Result** ✓ Passed**MOT #1** 2018-12-17 10:18**MOT test number** 153323728426**Result** ✗ Failed**Fail** Front Registration plate does not conform to the specified requirements honey comb effect background (0.1 (d))**Fail** Rear Registration plate does not conform to the specified requirements honey comb effect background (0.1 (d))



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
21 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	21 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	B
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-



Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners did this LEXUS have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this LEXUS had different number plates.

Number of plates	1
Current registration	LL65JKE
Plate since	2019-09-29
Current registration	LL65JKE
Plate since	2019-09-29

More info >



Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LEXUS is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-12-18
Last registration	2023-09-19
Complete history	See info



Registration #1	2015-12-18	27 mi
Registration #2	2018-12-17	21.088 mi
Registration #3	2018-12-18	21.101 mi
Registration #4	2019-11-21	27.124 mi
Registration #5	2020-11-30	31.825 mi
Registration #6	2020-12-22	31.877 mi
Registration #7	2020-12-22	31.877 mi
Registration #8	2020-12-22	31.877 mi
Registration #9	2020-12-22	31.877 mi
Registration #10	2020-12-22	31.877 mi

More info >



Car features

The LEXUS factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete LEXUS factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	85%
Pedestrian	80%
Safety systems	66%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1430 mm
Length	4665 mm
Wheel base	2800 mm
Kerb weight	1720 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	2AR1360283