





General information

| Make | MINI |
|---------------------|----------------|
| Model | ONE |
| Colour | Blue |
| Year of manufacture | 2016 |
| Top speed | 119 mph |
| 0 - 60 mph | 10.1 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 101 BHP |
|-------------------------|---------------------|
| Max. torque | 180 Nm at 1.400 rpm |
| Engine capacity | 1.198 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 47.9 mpg |
| Consumption extra urban | 67.3 mpg |
| Consumption combined | 58.9 mpg |
| CO2 emission | 112 g/km |
| CO2 label | С |







Internet history

Entry 1

Date Pictures 2021-07-25

15

Listing price

View report



source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-07-05 |
|--------------------|------------|
| MOT pass rate | 71 % |
| MOT passed | 5 |
| Failed MOT tests | 2 |
| Total advice items | 4 |
| Total items failed | 2 |

| MOT #7 | 2023-07-05 15:45 |
|--|------------------|
| MOT test number | 917047082905 |
| Result | 🗸 Passed |
| Next expiry date 2024-07-0 | |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #6 | 2022-07-0 |)6 11:13 |
|--|---|----------|
| MOT test | number 920917 | 972837 |
| Result | | Passed |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) | | |

| MOT #5 | 2021-06-16 14:10 |
|-----------------|------------------|
| MOT test number | 861028460203 |
| Result | ✓ Passed |
| | |
| | |

| MOT #4 | 2020-07-06 14:55 |
|-----------------|------------------|
| MOT test number | 487979701718 |
| Result | ✓ Passed |





| MOT #3 | 2020-07-06 08:10 | |
|--|------------------|--|
| MOT test number | 603815446614 | |
| Result | 🗙 Failed | |
| Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords plus bald on the outer edges. (5.2.3 (d) (i)) | | |
| Fail Offside Front Windscreen wiper does not clear the windscreen effectively (| 3.4 (b) (ii)) | |
| | | |
| MOT #2 | 2019-06-20 07:22 | |
| MOT test number | 641472085410 | |
| Result | Passed | |
| | | |
| MOT #1 | 2019-06-19 14:34 | |
| MOT test number | 447860865648 | |
| Result | 🗙 Failed | |
| Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords | | |

(5.2.3 (d) (i))



Tax & MOT check

| Tax due: 1 August 2024 | ✓ Taxed | Expires: 5 July 2024 | ✓ МОТ |
|----------------------------------|------------|--------------------------------|----------------------|
| Tax status | | | Valid until 1 August |
| Days left | | | 94 |
| MOT expiry date | | | 5 July 2024 |
| Full MOT history | | | See MOT history |
| Tax calculation | | | |
| Vahiele elece | | 40 | |

| Vehicle class | 48 |
|---|----------------|
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------|
| Date | |
| Category | Lamp |
| Туре | K K K |
| Damage 2 | AMPL |
| | F Store |
| Date | 1. F |
| Category | ant |
| Туре | |

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this MINI had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | More info > |





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2016-06-23 |
| Last registration | 2023-07-05 |
| Complete history | See info |



| Registration #1 | 2016-06-23 | 23 mi |
|-----------------|------------|------------|
| Registration #2 | 2019-06-19 | 32.528 mi |
| Registration #3 | 2019-06-20 | 32.528 mi |
| Registration #4 | 2020-07-06 | 39.441 mi |
| Registration #5 | 2020-07-06 | 39.441 mi |
| Registration #6 | | 11.177 esi |
| Registration #7 | | 11.777 esi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 esi |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| 50482 | |
| \$0501 | |
| \$0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

**** see crash video



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1727 mm |
| Height | 1425 mm |
| Length | 3982 mm |
| Wheel base | 2567 mm |
| Kerb weight | 1225 kg |
| Max. allowed weight | 1680 kg |
| Additional information | |
| Fuel tank capacity | 40 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|----------|
| Engine number | G193H389 |