





report date: 2024-03-28

General information

Make	PEUGEOT
Model	2008 S/S ALLURE
Colour	Grey
Year of manufacture	2018
Top speed	124 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	68.9 mpg
Consumption combined	58.9 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/12



CY18UBO

report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-29

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-18
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	18
Total items failed	5

MOT #6		2024-04-17 09:50
MOT test	number	577463972345
Result		✓ Passed
Next exp	iry date	2025-04-18
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor (6.1.7 (g)	Offside Front Drive shaft joint constant velocity boot severely deteriorated Sr (i))	mall hole in the boot

CarCheck.co.uk page 3/12



CY18UBO

report date: 2024-03-28

MOT #5 2024-04-17 09:50 **MOT** test number 148207138035 Result × Failed Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Pass with rectification Nearside Front Headlamp aim too high (4.1.2 (a)) Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Pass with rectification Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated Small hole in the boot (6.1.7 (g) (i)) Pass with rectification Offside Front Headlamp aim too high (4.1.2 (a)) **Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT test number

801969447147

Result

✓ Passed

Minor

Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor

Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

CarCheck.co.uk page 4/12



CY18UBO

report date: 2024-03-28

2023-04-11 14:02 **MOT** #3 971330505494 **MOT test number** Result × Failed **Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a)) Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a))

MOT #2	2022-04-19 07:50
MOT test number	380316409488
Result	✓ Passed
MOT #1	2021-09-04 11:27
MOT test number	614007795645
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	18 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NIS UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-08-20
Last registration	2024-04-17
Complete history	See info



Registration #1	2018-08-20	18 mi
Registration #2	2021-09-04	18.637 mi
Registration #3		11.777 es
Registration #4	2022-04-19	18.693 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		

More info >

page 11/12 CarCheck.co.uk



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	88%
Children	77%
Pedestrian	72%
Safety systems	70%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1829 mm
Height	1556 mm
Length	4159 mm
Wheel base	2538 mm
Kerb weight	1160 kg
Max. allowed weight	1675 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	ge 12/12

Number of axles 2

Engine number XTA30933026