





report date: 2024-03-28

General information

Make	FORD
Model	S-MAX ZETEC TDCI
Colour	Black
Year of manufacture	2010
Top speed	129 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	49.6 mpg
CO2 emission	152 g/km
CO2 label	G



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history


Entry 2

Date 2021-12-28

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-12-27
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2024-10-20
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	8
Total items failed	3

MOT #12	2023-10-18 12:11
MOT test number	158991620809
Result	✓ Passed
Next expiry date	2024-10-20
Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i))	

MOT #11	2022-10-11 11:36
MOT test number	574825572986
Result	✓ Passed
Advice Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	

MOT #10		2021-09-22 18:07
MOT test	number	659832920970
Result		✓ Passed
Advice	Rear Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #9	2020-10-13 14:32
MOT test	number 762748184395
Result	✓ Passed
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Both rear trailing arm bushes slightly perished

Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	
Advice	Both rear trailing arm bushes slightly perished	
MOT #8		2019-10-01 09:53
MOT test nu	umber	374072862478
Result		✓ Passed
MOT #7		2018-10-04 10:06
MOT test nu	ımber	797568641799
Result		✓ Passed
MOT #6		2017-10-18 08:57
MOT test nu	ımber	336083464654
Result		✓ Passed
MOT #5		2016-10-06 14:47
MOT test nu	ımber	390324683947
Result		✓ Passed
MOT #4		2016-10-06 12:18
MOT test nu	ımber	130324348277
Result		★ Failed

MOT test number		130324348277
Result		× Failed
Fail	Nearside Front Front position lamp(s) not working (1.1.A.3b)	
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

CarCheck.co.uk page 4/11



report date: 2024-03-28

MOT #3		2015-10-14 11:19
MOT test	number	499292375558
Result		✓ Passed
MOT #2		2014-10-10 09:54
MOT test	number	375443284293
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2013-10-17 09:32
MOT test number	125260093275
Result	✓ Passed

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have?		
Check it in the premium report and see all owner registrations. Download the full report in	<u>nere</u> .	
manage of the same		

	More info >	
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates	,	
Current registration	UK NE	
Plate since		
Current registration	OK SIE	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-10-20
Last registration	2023-10-18
Complete history	See info



Registration #1	2010-10-20	12 mi
Registration #2	2013-10-17	84.000 mi
Registration #3	2014-10-10	96.843 mi
Registration #4	2015-10-14	112.467 mi
Registration #5	2016-10-06	127.169 mi
Registration #6	2016-10-06	127.169 mi
Registration #7	2017-10-18	144.115 mi
Registration #8	2018-10-04	159.522 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

50225	Air conditionin
50295	
60482	
60501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2154 mm
Height	1764 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1733 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats	7	
Number of axles Carcheck.co.uk	2 pag	e 11/11