



PK09EEW

report date: 2024-03-28

General information

Make	MAZDA
Model	5 TS2
Colour	Red
Year of manufacture	2009
Top speed	113 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-01-17
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-31
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	36
Total items failed	3

MOT #17 2024-01-25 11:42

MOT test number 196764452699

Result ✓ Passed

Next expiry date 2025-01-31

- Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Inner Integral body structure is corroded but structural rigidity is not significantly reduced cill (6.1.1 (c) (i))
- Advice** Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Inner Integral body structure is corroded but structural rigidity is not significantly reduced cill (6.1.1 (c) (i))

MOT #16 2023-01-25 09:14

MOT test number 229242999495

Result ✓ Passed

Advice Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Integral body structure is corroded but structural rigidity is not significantly reduced inner and outer cill (6.1.1 (c) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Integral body structure is corroded but structural rigidity is not significantly reduced inner and outer cill (6.1.1 (c) (i))

**MOT #15** 2022-02-01 08:34**MOT test number** 433239903138**Result** Passed**MOT #14** 2022-01-30 09:25**MOT test number** 811064288264**Result** Failed

- MAJOR** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- MAJOR** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- MAJOR** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- MAJOR** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- MAJOR** Rear Registration plate missing (0.1 (a))

MOT #13 2021-03-10 10:51**MOT test number** 895187315342**Result** Passed

- Advice** Exhaust heatshield loose @ fuel tank

MOT #12 2020-03-16 14:53**MOT test number** 157414729510**Result** Passed

- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #11** 2020-03-16 11:28**MOT test number** 444530131009**Result** ✗ Failed**Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #10** 2019-02-20 09:23**MOT test number** 252498240761**Result** ✓ Passed**MOT #9** 2018-03-05 12:28**MOT test number** 174973748772**Result** ✓ Passed**MOT #8** 2018-03-05 09:17**MOT test number** 561162268720**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Offside Front Lower Ball joint has excessive play (2.2.B.1f)**MOT #7** 2017-03-15 09:15**MOT test number** 129413514222**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #6** 2016-02-18 09:36**MOT test number** 121749691176**Result** ✓ Passed**MOT #5** 2015-03-11 10:41**MOT test number** 649110575020**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2014-03-17 13:41**MOT test number** 445616874010**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-03-13 15:15**MOT test number** 349252774049**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2013-03-07 10:53
MOT test number	177046763414
Result	✓ Passed

MOT #1	2012-03-13 13:14
MOT test number	139013172425
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
31 January 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	31 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	PK09EEW
Plate since	2019-09-28
Current registration	PK09EEW
Plate since	2019-09-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX XXXX
Date of agreement	XXXXXXXXXX XXXX
Agreement type	XXXXXXXXXX XXXX
Agreement term	XXXXXXXXXX XXXX
Agreement number	XXXXXXXXXX XXXX
Contact info	XXXXXXXXXX XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-17
Last registration	2024-01-25
Complete history	See info



Registration #1	2009-03-17	6 mi
Registration #2	2012-03-13	20.188 mi
Registration #3	2013-03-07	26.457 mi
Registration #4	2014-03-13	33.674 mi
Registration #5	2014-03-17	33.817 mi
Registration #6	2015-03-11	39.979 mi
Registration #7	2016-02-18	46.152 mi
Registration #8	2017-03-15	52.878 mi
Registration #9	2018-03-05	60.508 mi
Registration #10	2018-03-05	60.508 mi
Registration #11	2019-03-05	60.508 mi
Registration #12	2019-03-05	60.508 mi
Registration #13	2019-03-05	60.508 mi
Registration #14	2019-03-05	60.508 mi
Registration #15	2019-03-05	60.508 mi
Registration #16	2019-03-05	60.508 mi
Registration #17	2019-03-05	60.508 mi
Registration #18	2019-03-05	60.508 mi
Registration #19	2019-03-05	60.508 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1615 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1400 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	L8 20269237