



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	S-Class S320L CDI
Colour	Blue
Year of manufacture	2007
Top speed	149 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	540 Nm at 1.600 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	24.1 mpg
Consumption extra urban	43.5 mpg
Consumption combined	33.6 mpg
CO2 emission	223 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-09-17
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	37
Total items failed	9

MOT #19 2023-09-18 14:40

MOT test number 909143377308

Result ✓ Passed

Next expiry date 2024-09-17

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor** Offside Front Outer Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18 2022-06-10 13:37

MOT test number 185149872968

Result ✓ Passed

**MOT #17**

2022-02-07 17:01

**MOT test number**

940118480407

**Result**

✗ Failed

**Fail** Offside Front Lower Suspension arm ball joint excessively worn rear arm (5.3.4 (a) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Fail** Emissions not tested engine noise and smoke (8.2.2.2 (e))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn rear arm (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**MOT #16**

2021-06-02 16:21

**MOT test number**

942505558135

**Result**

✓ Passed

**Advice** Front Suspension arm ball joint has slight play both side (5.3.4 (a) (i))**MOT #15**

2021-05-30 11:11

**MOT test number**

270280904486

**Result**

✓ Passed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #14**

2021-05-25 09:05

**MOT test number**

321849906820

**Result****✗ Failed****Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Exhaust emissions exceed manufacturer's specified limit Manufacturer's specified limit 0.50 (8.2.2.2 (a))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Headlamps matched pair are not the same colour (4.1.4 (d))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #13**

2020-10-31 11:53

**MOT test number**

536668457837

**Result****✓ Passed****Advice** Front Wheel bearing has slight play Both (5.1.3 (a) (i))**MOT #12**

2019-10-30 14:26

**MOT test number**

751198719109

**Result****✓ Passed****Advice** Engine covers and under shields fitted restricting the view of some components**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #11** 2018-11-03 11:51**MOT test number** 478409088084**Result** ✓ Passed**Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Small chip in windscreen**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Engine covers and under shields fitted restricting the view of some components**MOT #10** 2017-10-18 12:49**MOT test number** 313635460883**Result** ✓ Passed**Advice** Both rear tyres getting low on tread**Advice** Engine cover and under tray fitted obstruct view**MOT #9** 2016-10-17 10:11**MOT test number** 326057559778**Result** ✓ Passed**Advice** Engine cover and under tray fitted obstruct view**MOT #8** 2015-10-08 13:19**MOT test number** 819983891284**Result** ✓ Passed**MOT #7** 2014-10-23 11:01**MOT test number** 706816094218**Result** ✓ Passed

**MOT #6** 2013-10-01 14:46**MOT test number** 889864573255**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #5** 2012-10-12 11:22**MOT test number** 726026582208**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-10-12 11:22**MOT test number** 285406782219**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-10-03 09:43**MOT test number** 485126471239**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #2** 2010-10-06 16:26**MOT test number** 521439470243**Result** ✓ Passed



MOT #1	2010-10-06 12:38
MOT test number	603129570210
Result	✗ Failed
Fail	Parking brake: efficiency below requirements (3.7.B.7)





Tax & MOT check

X

Untaxed

Tax expired:  
18 April 2024

✓

MOT

Expires:  
17 September 2024

Tax status	Expired at 18 April 2024
Days left	10 days too late
MOT expiry date	17 September 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-10-29
Last registration	2023-09-18
Complete history	<a href="#">See info</a>



Registration #1	2007-10-29	27 mi
Registration #2	2010-10-06	63.799 mi
Registration #3	2010-10-06	63.799 mi
Registration #4	2011-10-03	83.847 mi
Registration #5	2012-10-12	102.278 mi
Registration #6	2013-10-01	119.814 mi
Registration #7	2014-10-23	126.672 mi
Registration #8	2015-10-08	129.065 mi
Registration #9	2016-10-17	132.726 mi
Registration #10	2017-10-18	135.786 mi
Registration #11	2018-10-20	138.847 mi
Registration #12	2019-10-20	141.908 mi
Registration #13	2020-10-20	144.969 mi
Registration #14	2021-10-20	148.030 mi
Registration #15	2022-10-20	151.091 mi
Registration #16	2023-10-20	154.152 mi
Registration #17	2024-10-20	157.213 mi
Registration #18	2025-10-20	160.274 mi
Registration #19	2026-10-20	163.335 mi
Registration #20	2027-10-20	166.396 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1872 mm
Height	1473 mm
Length	5076 mm
Wheel base	3165 mm
Kerb weight	2010 kg
Max. allowed weight	2580 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64293040549243