



PEUGEOT



DE6ICXD


report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 HDI ACTIVE
Colour	Grey
Year of manufacture	2011
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	110 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-07-31
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT expiry date</b>	2024-08-02
<b>MOT pass rate</b>	63 %
<b>MOT passed</b>	10
<b>Failed MOT tests</b>	6
<b>Total advice items</b>	10
<b>Total items failed</b>	19

<b>MOT #16</b>	2023-07-13 11:15
<b>MOT test number</b>	903062567291
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-08-02

<b>MOT #15</b>	2023-07-13 10:45
<b>MOT test number</b>	447525375224
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))

<b>MOT #14</b>	2022-07-26 10:13
<b>MOT test number</b>	104399373133
<b>Result</b>	✓ Passed

<b>MOT #13</b>	2021-08-03 11:38
<b>MOT test number</b>	718237142636
<b>Result</b>	✓ Passed

<b>MOT #12</b>	2020-11-18 12:26
<b>MOT test number</b>	311387117231
<b>Result</b>	✓ Passed

**MOT #11** 2020-11-18 10:27**MOT test number** 402432734898**Result** ✗ Failed

**Fail** Offside Headlamp aim projected beam image is obviously incorrect Bulb looks to be incorrectly fitted.  
(4.1.2 (c))

**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #10** 2019-11-18 10:58**MOT test number** 924913952459**Result** ✓ Passed**MOT #9** 2019-11-15 15:57**MOT test number** 363449331611**Result** ✗ Failed

**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Fail** Windscreen washer not working (3.5 (a))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources  
(4.7.1 (b) (i))

**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

**Fail** Exhaust system insecure both exhaust brackets broken (6.1.2 (a))

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords  
195/55/16 (5.2.3 (d) (i))

**MOT #8** 2018-11-22 16:36**MOT test number** 195748340322**Result** ✓ Passed

**MOT #7** 2018-11-22 10:43**MOT test number** 685208506325**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Nail to tread/puncture**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #6** 2017-11-06 16:57**MOT test number** 161306965074**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2017-11-06 15:08**MOT test number** 784507292381**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Exhaust system not adequately supported front and rear brackets broken (7.1.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #4	2016-10-07 15:55
MOT test number	973749594308
Result	✓ Passed
MOT #3	2016-10-07 08:15
MOT test number	893099269638
Result	✗ Failed
<div><div>Fail</div>Registration plate lamp not working (1.1.C.1d)</div> <div><div>Fail</div>Offside Rear wheel bearing rough when rotated (2.6.1)</div>	
MOT #2	2015-10-01 08:04
MOT test number	357450991234
Result	✓ Passed
MOT #1	2014-10-01 09:16
MOT test number	258334874219
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
2 August 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	2 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-09-30
Last registration	2023-07-13
Complete history	<a href="#">See info</a>



Registration #1	2011-09-30	12 mi
Registration #2	2014-10-01	46.003 mi
Registration #3	2015-10-01	58.773 mi
Registration #4	2016-10-07	72.019 mi
Registration #5	2016-10-07	72.019 mi
Registration #6	2017-11-06	85.760 mi
Registration #7	2017-11-06	85.760 mi
Registration #8	2018-11-22	93.540 mi
Registration #9	2018-11-22	93.540 mi
Registration #10	2019-05-29	93.540 mi
Registration #11	2019-05-29	93.540 mi
Registration #12	2019-05-29	93.540 mi
Registration #13	2019-05-29	93.540 mi
Registration #14	2019-05-29	93.540 mi
Registration #15	2019-05-29	93.540 mi
Registration #16	2019-05-29	93.540 mi
Registration #17	2019-05-29	93.540 mi
Registration #18	2023-07-13	93.540 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1498 mm
Length	4276 mm
Wheel base	2608 mm
Kerb weight	1410 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	JBEE0019176