



YF56FSS

report date: 2024-03-28

General information

Make	FIAT
Model	SCUDO JTD SX DYNAMIC P/V
Colour	White
Year of manufacture	2006
Gearbox	5 speed Manual

Engine & fuel consumption

Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-03
Pictures	46
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2023-12-07
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	49
Total items failed	4



MOT #17	2023-12-19 14:56
MOT test number	745175551745
Result	✖ Failed

**DANGEROUS** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**DANGEROUS** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Advice** Central Front Exhaust mounting defective (6.1.2 (a))

**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))

**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**DANGEROUS** Offside Front Outer Vehicle structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired sill (6.2.2 (d) (ii))

**MAJOR** Nearside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

**DANGEROUS** Nearside Rear Outer Vehicle structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired (6.2.2 (d) (ii))

**MAJOR** Offside Front Seat belt damaged (7.1.2 (b) (i))

**MAJOR** Offside Rear Brake pipe excessively corroded drum inwards (1.1.11 (c))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**DANGEROUS** Nearside Front Outer Vehicle structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired sill (6.2.2 (d) (ii))

**Advice** Offside Front Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security engine mounting under bonnet (6.2.2 (d) (i))

**DANGEROUS** Offside Front Inner Vehicle structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired sill (6.2.2 (d) (ii))

**MAJOR** Offside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

**DANGEROUS** Offside Rear Outer Vehicle structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired sill (6.2.2 (d) (ii))

**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #16** 2022-12-08 18:03**MOT test number** 628868963640**Result** ✓ Passed**MOT #15** 2021-09-27 14:12**MOT test number** 581114428987**Result** ✓ Passed**MOT #14** 2021-03-15 09:52**MOT test number** 869818205838**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** All underside showing signs of corrosion**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security sill (6.2.2 (d) (i))**MOT #13** 2021-03-15 09:52**MOT test number** 748661919627**Result** ✗ Failed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Pass with rectification** Nearside Headlamp aim too far to the left (4.1.2 (a))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security sill (6.2.2 (d) (i))**Advice** All underside showing signs of corrosion

**MOT #12**

2020-02-07 15:07

**MOT test number**

193130722729

**Result**

✓ Passed

**Advice**

Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #11**

2020-02-03 14:06

**MOT test number**

528227385725

**Result**

✗ Failed

**Minor**

Indicator switch faulty offside position (4.4.2 (a) (i))

**MAJOR**

Offside Front Service brake excessively fluctuating (1.2.1 (e))

**Advice**

Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**DANGEROUS**

Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

**MAJOR**

Nearside Front Service brake excessively fluctuating (1.2.1 (e))

**Advice**

Exhaust has a minor leak of exhaust gases various places (6.1.2 (a))

**DANGEROUS**

Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

**MOT #10**

2019-02-01 16:30

**MOT test number**

446839442640

**Result**

✓ Passed

**Advice**

Subframe corroded but not excessive

**Advice**

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9** 2018-02-21 18:37**MOT test number** 477256358779**Result** ✓ Passed**Advice** Front subframe corroded but not excessive**Advice** Nearside handbrake cable clips broken but cable still secure**MOT #8** 2018-02-19 13:06**MOT test number** 123121676919**Result** ✗ Failed**Fail** Offside Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a)**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Nearside handbrake cable clips broken but cable still secure**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Front subframe corroded but not excessive**MOT #7** 2017-02-17 16:50**MOT test number** 837055352143**Result** ✓ Passed**Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)**MOT #6** 2016-02-17 16:00**MOT test number** 687142740504**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)





<b>MOT #5</b>	2014-11-14 10:21
---------------	------------------

<b>MOT test number</b>	448568414347
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
---------------	---

<b>MOT #4</b>	2013-11-15 11:47
---------------	------------------

<b>MOT test number</b>	658679813397
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2012-01-16 13:43
---------------	------------------

<b>MOT test number</b>	735246212017
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2011-01-20 10:48
---------------	------------------

<b>MOT test number</b>	736580221020
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2010-01-21 10:28
---------------	------------------

<b>MOT test number</b>	833831220020
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✕  
Untaxed

Tax expired:  
31 January 2024

✕  
MOT

Expired:  
7 December 2023

Tax status	Expired at 31 January 2024
Days left	89 days too late
MOT expiry date	7 December 2023
Full MOT history	<a href="#">See MOT history</a>



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-11-30
Last registration	2023-12-19
Complete history	<a href="#">See info</a>



Registration #1	2006-11-30	28 mi
Registration #2	2010-01-21	23.767 mi
Registration #3	2011-01-20	27.581 mi
Registration #4	2012-01-16	34.631 mi
Registration #5	2013-11-15	47.239 mi
Registration #6	2014-11-14	62.046 mi
Registration #7	2016-02-17	81.565 mi
Registration #8	2017-02-17	86.535 mi
Registration #9	2018-02-19	89.157 mi
Registration #10	2018-02-21	89.157 mi
Registration #11	2019-05-20	95.377 mi
Registration #12	2019-05-20	95.377 mi
Registration #13	2019-05-20	95.377 mi
Registration #14	2019-05-20	95.377 mi
Registration #15	2019-05-20	95.377 mi
Registration #16	2019-05-20	95.377 mi
Registration #17	2019-05-20	95.377 mi
Registration #18	2019-05-20	95.377 mi
Registration #19	2019-05-20	95.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1435 mm
Max. allowed weight	2330 kg

Additional information

Number of seats	3
Number of axles	2
Engine number	3027276