



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE NON FAP DCI 130
Colour	Gold
Year of manufacture	2007
Top speed	126 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.870 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-09
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-11-04
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	30
Total items failed	30

MOT #21	2021-11-03 11:41
MOT test number	171012529260
Result	✓ Passed
Next expiry date	2022-11-04
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #20**

2021-11-03 08:43

MOT test number

296563133161

Result**✗ Failed**

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #19

2020-11-05 12:42

MOT test number

881136289897

Result**✓ Passed**

- Advice** All suspension parts corroded
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Under vehicle parts corroded
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #18** 2020-11-05 12:42**MOT test number** 908876260657**Result** ✗ Failed**Advice** All suspension parts corroded**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Under vehicle parts corroded**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #17** 2019-10-02 15:08**MOT test number** 403542703763**Result** ✓ Passed**Advice** Road wheel slightly distorted ALL FOUR ON INSIDE (5.2.2 (c) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened All four (1.1.14 (a) (ii))**MOT #16** 2019-10-02 08:18**MOT test number** 129725911074**Result** ✗ Failed**Advice** Brake disc worn, pitted or scored, but not seriously weakened All four (1.1.14 (a) (ii))**Fail** Rear Exhaust system insecure (6.1.2 (a))**Advice** Road wheel slightly distorted ALL FOUR ON INSIDE (5.2.2 (c) (i))**Fail** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Central Exhaust system insecure (6.1.2 (a))

**MOT #15** 2018-10-16 14:01**MOT test number** 274088128006**Result** ✓ Passed**MOT #14** 2017-08-09 09:35**MOT test number** 502677770690**Result** ✓ Passed**MOT #13** 2016-08-12 14:39**MOT test number** 582754708369**Result** ✓ Passed**MOT #12** 2016-08-12 11:33**MOT test number** 835229110870**Result** ✗ Failed

- Fail** Nearside Steering arm has relative movement at its fixings (2.2.B.1h)
- Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)

MOT #11 2015-09-29 07:50**MOT test number** 668483336621**Result** ✓ Passed

- Advice** Play in steering rack inner joints

**MOT #10** 2015-09-25 15:40**MOT test number** 831104655126**Result** ✗ Failed

- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Offside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)
- Advice** Play in steering rack inner joints
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

MOT #9 2014-10-21 12:06**MOT test number** 597854394239**Result** ✓ Passed

- Notice** Both front strut top bearings sticking

MOT #8 2014-10-21 12:06**MOT test number** 445084994227**Result** ✗ Failed

- Pass with rectification** Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Notice** Both front strut top bearings sticking
- Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)

MOT #7 2013-10-05 13:58**MOT test number** 798058773275**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2012-09-28 15:50**MOT test number** 288802172208**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-09-28 14:51**MOT test number** 156592172235**Result** ✗ Failed**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2011-09-28 15:41**MOT test number** 348511171274**Result** ✓ Passed**MOT #3** 2011-09-28 11:26**MOT test number** 417951771244**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear wheel bearing has excessive play (2.6.2)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Rear wheel bearing has excessive play (2.6.2)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



MOT #2	2010-09-01 10:56
MOT test number	472524440271
Result	✓ Passed

MOT #1	2010-09-01 10:56
MOT test number	992694240234
Result	✗ Failed
<div>Pass with rectification</div> Nearside Headlamp not working on dipped beam (1.7.5a)	



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	HV57RXX
Plate since	2019-03-28
Current registration	HV57RXX
Plate since	2019-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-28
Last registration	2021-11-03
Complete history	See info



Registration #1	2007-09-28	14 mi
Registration #2	2010-09-01	25.202 mi
Registration #3	2011-09-28	30.111 mi
Registration #4	2011-09-28	30.116 mi
Registration #5	2012-09-28	38.750 mi
Registration #6	2012-09-28	38.750 mi
Registration #7	2013-10-05	48.286 mi
Registration #8	2014-10-21	63.027 mi
Registration #9	2015-09-25	68.026 mi
Registration #10	2015-09-29	68.027 mi
Registration #11	2016-08-12	68.085 mi
Registration #12	2016-08-12	68.085 mi
Registration #13	2016-08-12	68.085 mi
Registration #14	2016-08-12	68.085 mi
Registration #15	2016-08-12	68.085 mi
Registration #16	2016-08-12	68.085 mi
Registration #17	2016-08-12	68.085 mi
Registration #18	2016-08-12	68.085 mi
Registration #19	2016-08-12	68.085 mi
Registration #20	2016-08-12	68.085 mi
Registration #21	2016-08-12	68.085 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2026 mm
Height	1404 mm
Length	4355 mm
Wheel base	2522 mm
Kerb weight	1430 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	C034488