





report date: 2024-03-28

General information

Make	MINI
Model	MINI (R60) COOPER SD
Colour	Black
Year of manufacture	2012
Top speed	121 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	141 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-03

Pictures 3

Listing price <u>View report</u>







source: cargurus.co.uk

CarCheck.co.uk page 2/12



MM12RCZ report date: 2024-03-28

MOT history

MOT expiry date	2024-09-26
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #10	2023-09-01 12:03
MOT test number	507559954405
Result	✓ Passed
Next expiry date	2024-09-26

MOT #9		2022-09-23 09:29
MOT test	number	465464561876
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #8	2021-09-27 10:35
MOT test number	404122733950
Result	✓ Passed
Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Exhaust has a minor leak of exhaust gases from under bonnet (6.1.2 (a))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #7		2020-11-17 14:04
MOT test	number	401201482471
Result		✓ Passed
MOT #6		2019-07-16 13:07
MOT test	number	214181528938
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Nail in tyre	

MOT #5	2018-06-15 11:43
MOT test number	394791539323
Result	✓ Passed
MOT #4	2017-06-06 12:45
MOT test number	526187547155
Result	✓ Passed
MOT #3	2016-06-10 14:32
MOT test number	529420363149
Result	✓ Passed
Advice Offside Rear tyre has had puncture repair	

MOT #2	2015-06-11 10:30
MOT test number	425092765123
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2015-06-10 11:21 MOT test number 529681765119

Result × Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 5/12



MM12RCZ report date: 2024-03-28

Tax & MOT check





Expires: 26 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	26 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



faste since

MM12RCZ

report date: 2024-03-28

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this MINI had different number plates.

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-08-16
Last registration	2023-09-01
Complete history	See info



Registration #1	2012-08-16	26 mi
Registration #2	2015-06-10	28.214 mi
Registration #3	2015-06-11	28.242 mi
Registration #4	2016-06-10	37.657 mi
Registration #5	2017-06-06	45.302 mi
Registration #6	2018-06-15	53.981 mi
Registration #7		91,777 esi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1345 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	47	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number 72848233