



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO LIFE 16V TWINPORT
Colour	Blue
Year of manufacture	2009
Top speed	104 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.1 mpg
CO2 emission	148 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-05
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-14
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	24
Total items failed	3

MOT #18 2024-02-12 09:51

MOT test number 228693685319

Result ✓ Passed

Next expiry date 2025-02-14

Minor Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #17 2024-02-09 13:12

MOT test number 556239550138

Result ✗ Failed

MAJOR Offside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Minor Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MAJOR Nearside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #16**

2023-02-15 10:37

MOT test number

803455076710

Result

✓ Passed

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15**

2022-02-11 11:05

MOT test number

722808123247

Result

✓ Passed

MOT #14

2020-11-25 17:02

MOT test number

663169200296

Result

✓ Passed

Advice Offside Power steering component has slight seepage from a component Rack gaiter weeping (2.1.5 (a))**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #13**

2020-11-25 09:31

MOT test number

478641884741

Result

✗ Failed

Advice Offside Power steering component has slight seepage from a component Rack gaiter weeping (2.1.5 (a))**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #12** 2019-06-13 12:22**MOT test number** 997839098424**Result** ✓ Passed**MOT #11** 2019-06-11 10:02**MOT test number** 628415471792**Result** ✗ Failed**MAJOR** Rear Seat belt not functioning as intended inertia reel (7.1.2 (c))**Advice** Front Exhaust silencer slightly loose both clamps for both joins rusted off (8.1.1 (b) (i))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #10** 2018-06-19 08:42**MOT test number** 221893896055**Result** ✓ Passed**Advice** Front exhaust flexi deteriorated**MOT #9** 2017-06-16 09:47**MOT test number** 241201968597**Result** ✓ Passed**Advice** Offside Front tyre dead flat, possibly damaged**MOT #8** 2016-07-25 13:20**MOT test number** 387871983745**Result** ✓ Passed

**MOT #7** 2016-07-25 12:02**MOT test number** 818869855741**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear badly perished**MOT #6** 2015-06-27 08:24**MOT test number** 426478675128**Result** ✓ Passed**MOT #5** 2015-06-26 13:51**MOT test number** 978667175170**Result** ✗ Failed**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**MOT #4** 2014-10-29 14:34**MOT test number** 496152604425**Result** ✓ Passed**MOT #3** 2013-10-16 11:59**MOT test number** 418029583200**Result** ✓ Passed**MOT #2** 2012-11-28 12:59**MOT test number** 349573832383**Result** ✓ Passed



MOT #1	2012-01-18 16:36
MOT test number	189148112436
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
14 February 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	14 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-03-12
Last registration	2024-02-12
Complete history	See info



Registration #1	2009-03-12	19 mi
Registration #2	2012-01-18	13.925 mi
Registration #3	2012-11-28	18.196 mi
Registration #4	2013-10-16	23.862 mi
Registration #5	2014-10-29	27.989 mi
Registration #6	2015-06-26	29.055 mi
Registration #7	2015-06-27	29.055 mi
Registration #8	2016-07-25	33.892 mi
Registration #9	2016-07-25	33.892 mi
Registration #10	2017-06-16	35.036 mi
Registration #11	2019-05-29	35.277 mi
Registration #12	2019-05-29	35.277 mi
Registration #13	2019-05-29	35.277 mi
Registration #14	2019-05-29	35.277 mi
Registration #15	2019-05-29	35.277 mi
Registration #16	2019-05-29	35.277 mi
Registration #17	2019-05-29	35.277 mi
Registration #18	2019-05-29	35.277 mi
Registration #19	2019-05-29	35.277 mi
Registration #20	2019-05-29	35.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1950 mm
Height	1624 mm
Length	4042 mm
Wheel base	2630 mm
Kerb weight	1255 kg
Max. allowed weight	1810 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	19RY3632