





report date: 2024-03-29

General information

Make	FORD
Model	S-MAX GHIA TDCI
Colour	Blue
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-10

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT expiry date	2024-08-08
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	34
Total items failed	8

MOT #15	2023-08-09 16:46
MOT test number	774320281460
Result	✓ Passed
Next expiry date	2024-08-08
Advice Underbody covers / Trays Fitted	

MOT #14		2022-08-03 14:16
MOT test	number	775589357178
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear box exhaust deteriorated	
Advice (8.2.2.2 (c	Exhaust emits excessive smoke or vapour but not likely to obscure the vision))	on of other road users

MOT #13	2021-08-05 12:18
MOT test number	492043837862
Result	✓ Passed

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #12

MOT test number

913963224674

Result

Advice Offside door mirror loose

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11 2019-09-17 14:33 **MOT** test number 820431080668 Result ✓ Passed **MOT #10** 2019-09-17 12:03 **MOT test number** 928676523703 Result × Failed Fail Rear Exhaust silencer likely to become detached (8.1.1 (b) (ii)) **Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a)) Fail Exhaust has a major leak of exhaust gases (6.1.2 (a)) Fail Nearside Side repeater not working (4.4.1 (a) (ii)) Fail Offside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #9	2018-09-19 09:02
MOT test number	501596487191
Result	✓ Passed
Advice Central Exhaust has a minor leak of exhaust gases (6.1.2 (a)) Advice Fluid leak, but not excessive (8.4.1 (a) (i))	
Advice Fluid leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #8 2018-09-18 14:16

MOT test number 547458873261

Result X Failed

Advice Fluid leak, but not excessive (8.4.1 (a) (i))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #7 2017-09-14 10:50

MOT test number 917381435089

Result
✓ Passed

MOT #6 2016-09-16 10:49

MOT test number 380769330474

Result
✓ Passed

Advice Offside Rear Tyre worn close to the legal limit worn badly on inner edge, no cords exposed yet but it won't be long before they are, advise replacement, (4.1.E.1)

MOT #5 2015-09-01 14:21

MOT test number 160824902288

Advice Offside Rear Tyre worn close to the legal limit 225/45r18 (4.1.E.1)

Advice Unable to inspect underside of vehicle fully @ front due to under body covers fitted!.

Advice Offside Front Tyre worn close to the legal limit also worn excessively on the inner edge!.

225/45r18 (4.1.E.1)


Advice Unable to inspect engine compartment fully due to engine covers fitted


Advice Unable to inspect far rear seat belts due to seats x 2 stowed away!.

CarCheck.co.uk page 5/14



report date: 2024-03-29





CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #2 2013-09-18 13:10
MOT test number 985331663268

Result ✓ Passed

Notice Deep cut on nearside front tyre and nearside rear tyre wallk worn and damaged

Notice Oil leak

Advice Front Tyre worn close to the legal limit (4.1.E.1)

Notice Engine covers fitted obscuring some components in the engine bay

Notice Two of three child seats not connected

Notice Child seat fitted not allowing full inspection of adult belt

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Notice Under-trays fitted obscuring some underside components

Advice Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Windscreen appears to be excessively tinted

MOT #1 2012-07-28 11:17

MOT test number 366600012413

Result

Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	8 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
manus .	

manus .	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	OK SIE
Fiate since	mn.n.n
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-07-28
Last registration	2023-08-09
Complete history	See info



Registration #1	2009-07-28	27 mi
Registration #2	2012-07-28	18.910 mi
Registration #3	2013-09-18	25.353 mi
Registration #4	2014-09-18	30.954 mi
Registration #5	2014-09-19	30.954 mi
Registration #6	2015-09-01	36.093 mi
Registration #7	2016-09-16	40.907 mi
Registration #8	2017-09-14	45.457 mi
Registration #9	2018-09-18	49.868 mi
Registration #10		11.177 es
Registration #11		11.777 no
Registration #11 Registration #12		11.777 es
-		11.777 ea 11.777 ea 11.777 ea
Registration #12		11.777 ea 11.777 ea 11.777 ea
Registration #12 Registration #13		11.777 es 11.777 es 11.777 es 11.777 es
Registration #12 Registration #13 Registration #14		11.777 es 11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 14/14

Number of axles 2

Engine number 9K79192