



ADO7VYB

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN S TDI 105
Colour	Blue
Year of manufacture	2007
Top speed	111 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-04
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-03-24
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	36
Total items failed	6

MOT #17	2023-03-25 10:22
MOT test number	227019239746
Result	✓ Passed
Next expiry date	2024-03-24
Advice	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16	2022-03-19 09:35
MOT test number	311910238983
Result	✓ Passed

MOT #15	2021-03-08 14:09
MOT test number	991502544867
Result	✓ Passed

MOT #14	2020-03-17 15:58
MOT test number	804598632010
Result	✓ Passed
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #13** 2019-06-12 14:10**MOT test number** 300722824684**Result** ✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner tread (5.2.3 (e))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12 2018-06-11 11:06**MOT test number** 459301818898**Result** ✓ Passed

- Advice** Offside Rear Nail in tyre and worn on inner edge
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #11 2017-07-28 13:55**MOT test number** 830867874849**Result** ✓ Passed

- Advice** Offside Rear Bump stop deteriorated.
- Advice** Nearside Rear Bump stop deteriorated.
- Advice** Offside Rear Nail in tread. (not repairable)

**MOT #10**

2017-07-27 10:48

MOT test number

213885287622

Result

✗ Failed

Fail Rear Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Rear Nail in tread. (not repairable)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Advice** Offside Rear Bump stop deteriorated.**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Coolant level warning light on.**Advice** Nearside Rear Bump stop deteriorated.**Fail** Central Upper Stop lamp not working (1.2.1b)**MOT #9**

2016-06-20 11:43

MOT test number

247600300990

Result

✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8**

2015-06-08 12:46

MOT test number

589699255165

Result

✓ Passed

MOT #7

2014-06-16 12:36

MOT test number

919107464122

Result

✓ Passed

**MOT #6** 2013-06-14 16:47**MOT test number** 229015463404**Result** ✓ Passed

- Notice** Nail in rear tyre
- Advice** Offside Inner Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Tom tom fitted in middle of srceen
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Nearside Inner Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #5 2013-06-14 15:21**MOT test number** 938295963152**Result** ✗ Failed

- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Notice** Tom tom fitted in middle of srceen
- Advice** Nearside Inner Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Offside Inner Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nail in rear tyre

**MOT #4** 2012-06-14 15:19**MOT test number** 998186062199**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-06-14 13:31**MOT test number** 239776162458**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2011-06-16 16:32**MOT test number** 745047461109**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2010-05-26 12:43**MOT test number** 831256140149**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✗
MOT
Expired:
24 March 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	24 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-06-14
Last registration	2023-03-25
Complete history	See info



Registration #1	2007-06-14	21 mi
Registration #2	2010-05-26	30.867 mi
Registration #3	2011-06-16	41.144 mi
Registration #4	2012-06-14	51.610 mi
Registration #5	2012-06-14	51.611 mi
Registration #6	2013-06-14	64.351 mi
Registration #7	2013-06-14	64.323 mi
Registration #8	2014-06-16	74.091 mi
Registration #9	2015-06-08	82.430 mi
Registration #10	2016-06-20	91.915 mi
Registration #11	2016-06-20	91.915 mi
Registration #12	2016-06-20	91.915 mi
Registration #13	2016-06-20	91.915 mi
Registration #14	2016-06-20	91.915 mi
Registration #15	2016-06-20	91.915 mi
Registration #16	2016-06-20	91.915 mi
Registration #17	2016-06-20	91.915 mi
Registration #18	2016-06-20	91.915 mi
Registration #19	2016-06-20	91.915 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1539 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	BXE 542395