



report date: 2024-03-28

General information

Make	FORD
Model	FUSION FUSION +
Colour	Blue
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	204 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-12-04
Pictures	7
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-06
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	47
Total items failed	6

MOT #18	2024-02-28 11:16
MOT test number	599507372263
Result	✓ Passed
Next expiry date	2025-03-06
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #17**

2023-03-03 10:22

MOT test number

629750580237

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Front Tyre slightly damaged/cracking or perishing both tyres (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #16

2022-03-07 16:44

MOT test number

215177529975

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15

2022-02-28 17:49

MOT test number

288287834473

Result

✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Rear fog lamp not working (4.5.1 (a) (ii))

**MOT #14** 2021-04-06 09:30**MOT test number** 745556467041**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #13** 2020-04-07 09:42**MOT test number** 778728224038**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #12** 2020-04-07 09:42**MOT test number** 660499835422**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #11** 2019-04-10 09:56**MOT test number** 321065535169**Result** ✓ Passed**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front bumper damaged

**MOT #10** 2018-04-14 10:54**MOT test number** 745620968065**Result** ✓ Passed

- Advice** Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)
- Advice** Engine oil leak
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)

MOT #9 2018-04-14 10:54**MOT test number** 917586590075**Result** ✗ Failed

- Advice** Engine oil leak
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Offside Rear Rear fog lamp not working (1.3.2b)
- Advice** Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)

MOT #8 2017-01-16 17:06**MOT test number** 816360388739**Result** ✓ Passed**MOT #7** 2017-01-16 12:01**MOT test number** 662775029679**Result** ✗ Failed

- Fail** Rear Exhaust has a major leak of exhaust gases silencer holed and leaking (7.1.2)
- Fail** Central Rear Stop lamp not working high level stop lamp (1.2.1b)

**MOT #6** 2015-10-05 14:08**MOT test number** 654403740573**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases At pipe entry to rear silencer. (7.1.2)**Advice** Oil leak.**MOT #5** 2014-09-11 11:14**MOT test number** 366564354277**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-09-12 08:43**MOT test number** 368985253276**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Engine oil leak**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-09-07 09:59**MOT test number** 267501952270**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Sill covers fitted obscuring sills



MOT #2	2011-09-20 08:44
MOT test number	548443361202
Result	✓ Passed
Advice	Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2010-08-18 15:13
MOT test number	682010230266
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
6 March 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	6 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-09-29
Last registration	2024-02-28
Complete history	See info



Registration #1	2007-09-29	26 mi
Registration #2	2010-08-18	21.025 mi
Registration #3	2011-09-20	33.200 mi
Registration #4	2012-09-07	37.437 mi
Registration #5	2013-09-12	41.444 mi
Registration #6	2014-09-11	45.341 mi
Registration #7	2015-10-05	49.445 mi
Registration #8	2017-01-16	54.627 mi
Registration #9	2017-01-16	54.627 mi
Registration #10	2018-04-14	60.045 mi
Registration #11	2019-05-20	65.277 mi
Registration #12	2019-05-20	65.277 mi
Registration #13	2019-05-20	65.277 mi
Registration #14	2019-05-20	65.277 mi
Registration #15	2019-05-20	65.277 mi
Registration #16	2019-05-20	65.277 mi
Registration #17	2019-05-20	65.277 mi
Registration #18	2019-05-20	65.277 mi
Registration #19	2019-05-20	65.277 mi
Registration #20	2019-05-20	65.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1175 kg
Max. allowed weight	1670 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	7L62605