



HYUNDAI

LV6IXRU

report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Black
Year of manufacture	2012
Top speed	118 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	45.6 mpg
Consumption combined	39.2 mpg
CO2 emission	197 g/km
CO2 label	J






## Internet history

### Entry 3

Date	2022-09-11
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)

### Entry 2



Date	2021-08-14
Pictures	9
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)

### Entry 1

Date	2021-08-06
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://autotrader.co.uk)



## MOT history

MOT expiry date	2024-09-12
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	6
Total items failed	5

MOT #12	2023-09-06 11:12
MOT test number	773130398106
Result	✓ Passed
Next expiry date	2024-09-12
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
Minor	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #11	2022-09-13 11:14
MOT test number	371233886863
Result	✓ Passed

MOT #10	2021-08-25 16:25
MOT test number	790668684147
Result	✓ Passed

MOT #9	2021-01-20 11:55
MOT test number	197349851818
Result	✓ Passed

**MOT #8** 2021-01-18 11:38**MOT test number** 825164472580**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #7** 2019-06-18 12:00**MOT test number** 828556513027**Result** ✓ Passed**MOT #6** 2019-06-18 12:00**MOT test number** 539551818092**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #5** 2018-03-06 10:07**MOT test number** 815503232784**Result** ✓ Passed**MOT #4** 2018-03-06 10:07**MOT test number** 849948877972**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #3** 2017-03-07 09:43**MOT test number** 864924916285**Result** ✓ Passed



MOT #2	2016-02-12 14:28
MOT test number	419978771719
Result	✓ Passed

MOT #1	2015-01-14 10:54
MOT test number	155724815440
Result	✓ Passed
<div><div>Notice</div>Front registration plate cracked / deteriorated</div> <div><div>Notice</div>Nail in offside rear tyre</div> <div><div>Notice</div>Engine undertray fitted</div> <div><div>Notice</div>Offside front tyre worn very low on tread inner edge</div>	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
12 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	12 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>LV61XRU</b>
Plate since	2024-03-29
Current registration	<b>LV61XRU</b>
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-01-16
Last registration	2023-09-06
Complete history	<a href="#">See info</a>



Registration #1	2012-01-16	6 mi
Registration #2	2015-01-14	15.617 mi
Registration #3	2016-02-12	20.797 mi
Registration #4	2017-03-07	30.398 mi
Registration #5	2018-03-06	37.887 mi
Registration #6	2018-03-06	37.887 mi
Registration #7	2019-06-18	48.920 mi
Registration #8	2019-06-18	48.920 mi
Registration #9	2019-06-18	48.920 mi
Registration #10	2019-06-18	48.920 mi
Registration #11	2019-06-18	48.920 mi
Registration #12	2019-06-18	48.920 mi
Registration #13	2019-06-18	48.920 mi
Registration #14	2019-06-18	48.920 mi
Registration #15	2019-06-18	48.920 mi
Registration #16	2019-06-18	48.920 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1946 kg
Max. allowed weight	2570 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number

D4HBCU614953