



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS ZETEC TDCI
Colour	Black
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	204 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-30
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2022-05-22
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	13
Total items failed	10

MOT #14	2021-04-27 07:49
MOT test number	650036654599
Result	✓ Passed
Next expiry date	2022-05-22

MOT #13	2020-05-15 08:37
MOT test number	117814253035
Result	✓ Passed

MOT #12	2019-05-23 13:10
MOT test number	553693589913
Result	✓ Passed

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Minor** Nearside Registration plate lamp insecure (4.7.1 (c) (i))

**MOT #11**

2019-05-21 09:28

**MOT test number**

818263969475

**Result****✗ Failed**

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge 205/55 R16 91V (5.2.3 (e))

**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Minor** Nearside Registration plate lamp insecure (4.7.1 (c) (i))

**Fail** Nearside Front Position lamp not working (4.2.1 (a))

**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #10**

2018-09-28 08:48

**MOT test number**

651828292681

**Result****✓ Passed**

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement lower front arm inner rear bush (5.3.4 (a) (i))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement lower front arm inner rear bush (5.3.4 (a) (i))

**MOT #9**

2017-10-02 09:56

**MOT test number**

482334989516

**Result****✓ Passed**

**MOT #8** 2017-10-02 09:56**MOT test number** 434881772998**Result** ✗ Failed

**Pass with rectification** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)

**MOT #7** 2016-10-04 10:38**MOT test number** 645286566381**Result** ✓ Passed

**Advice** No D.M.S printout due to low emissions

**MOT #6** 2015-09-25 08:05**MOT test number** 907604929121**Result** ✓ Passed

**Advice** Note no D M S printout due to low emissions

**MOT #5** 2014-09-26 16:24**MOT test number** 539789964217**Result** ✓ Passed

**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #4** 2014-09-26 16:24**MOT test number** 249659164259**Result** ✗ Failed

**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)



MOT #3	2013-10-01 09:42
MOT test number	309054773400
Result	✓ Passed
<div>Notice</div> EHICLE TOO CLEAN TO GEGISTER C/O READING.	

MOT #2	2013-09-30 11:43
MOT test number	525663573228
Result	✗ Failed
<div>Fail</div> Offside Front Tyre has ply or cords exposed (4.1.D.1b)	
<div>Notice</div> EHICLE TOO CLEAN TO GEGISTER C/O READING.	

MOT #1	2012-09-04 11:54
MOT test number	336148742255
Result	✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
14 July 2021

✕  
MOT

Expired:  
22 May 2022

Tax status	Expired at 14 July 2021
Days left	1020 days too late
MOT expiry date	22 May 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>VO59ZPF</b>
Plate since	2019-03-28
Current registration	<b>VO59ZPF</b>
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-09-30
Last registration	2021-04-27
Complete history	<a href="#">See info</a>



Registration #1	2009-09-30	17 mi
Registration #2	2012-09-04	26.905 mi
Registration #3	2013-09-30	37.360 mi
Registration #4	2013-10-01	37.402 mi
Registration #5	2014-09-26	47.772 mi
Registration #6	2015-09-25	55.090 mi
Registration #7	2016-10-04	66.851 mi
Registration #8	2017-10-02	87.210 mi
Registration #9	2018-09-25	87.210 mi
Registration #10	2019-09-25	87.210 mi
Registration #11	2020-09-25	87.210 mi
Registration #12	2021-04-27	87.210 mi
Registration #13	2021-04-27	87.210 mi
Registration #14	2021-04-27	87.210 mi
Registration #15	2021-04-27	87.210 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1171 kg
Max. allowed weight	1675 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

9C73512