



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO COMBI CDTI
Colour	White
Year of manufacture	2014
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	290 Nm at 1.600 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	43.5 mpg
Consumption combined	38.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-17
Pictures	13
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-11-06
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	16
Total items failed	10

MOT #6	2023-11-06 11:33
MOT test number	963259427667
Result	✓ Passed
Next expiry date	2024-11-06
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 1.6MM (5.2.3 (e))

MOT #5	2023-11-01 16:48
MOT test number	323495671011
Result	✗ Failed
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Front Suspension arm ball joint excessively worn lower joint (5.3.4 (a) (i))
Fail	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 1.6MM (5.2.3 (e))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #4**

2022-11-07 13:16

MOT test number

718816104848

Result

✓ Passed

- Advice** Offside Rear Nail in tyre
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3

2022-11-07 12:12

MOT test number

556395633939

Result

✗ Failed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Nail in tyre
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Play in steering rack inner joint(s)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Hazard warning switch inoperative (4.4.2 (a) (ii))

MOT #2

2021-09-17 15:16

MOT test number

662498617894

Result

✓ Passed



MOT #1	2020-09-25 06:47
MOT test number	335707464089
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

✓
Taxed

Tax due:
1 November 2024

✓
MOT

Expires:
6 November 2024

Tax status		Valid until 1 November
Days left		187
MOT expiry date		6 November 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	VAUXH
Plate since	2024-03-28
Current registration	VAUXH
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2014-01-28
Last registration	2023-11-06
Complete history	See info



Registration #1	2014-01-28	11 mi
Registration #2	2020-09-25	109.697 mi
Registration #3	2021-09-17	113.633 mi
Registration #4	2022-09-25	113.633 mi
Registration #5	2023-09-25	113.633 mi
Registration #6	2023-09-25	113.633 mi
Registration #7	2023-09-25	113.633 mi
Registration #8	2023-09-25	113.633 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2206 mm
Height	1960 mm
Length	4782 mm
Kerb weight	1954 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	9
Engine number	NOT KNOWN