



WR58LCX

report date: 2024-03-28

General information

Make	FIAT
Model	BRAVO MULTIJET ACTIVE ECO
Colour	Silver
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	290 Nm at 1.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg





Internet history

Entry 2

Date	2021-07-22
Pictures	11
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-21
Pictures	11
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #13	2020-10-08 13:20
MOT test number	617881635841
Result	✓ Passed
Next expiry date	2021-10-29
Advice	Handbrake travel getting

MOT #12	2019-10-03 14:33
MOT test number	805101034954
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2019-09-30 16:30
MOT test number	683364893303
Result	✗ Failed
MAJOR	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
Advice	Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
MAJOR	Nearside Headlamp aim too low (4.1.2 (a))
Advice	Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #10**

2018-10-10 10:00

MOT test number

833089933495

Result

✓ Passed

- Advice** Rear exhaust silencer outer skin deteriorated
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Windscreen washer switch deteriorated
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #9

2017-10-04 13:33

MOT test number

591214953313

Result

✓ Passed

- Advice** Exhaust system excessively corroded but not leaking
- Advice** Gearbox stabilizing mounting has excessive play but secure
- Advice** Exhaust rubbers perishing

MOT #8

2016-10-03 13:44

MOT test number

679080495246

Result

✓ Passed

- Advice** Front brake discs heavily corroded
- Advice** Nearside Front Tyre worn close to the legal limit 3mm tyre worn very heavy on outer edges (4.1.E.1)
- Advice** Offside Front 4mm tyre worn heavier on edges
- Advice** Visual check of rear seatbelt with childseat
- Advice** Rear exhaust section heavily corroded
- Advice** Both front lower arm bushes slightly perishing

**MOT #7** 2015-10-30 15:14**MOT test number** 681435487811**Result** ✓ Passed**MOT #6** 2015-10-29 16:45**MOT test number** 579380111319**Result** ✗ Failed**Fail** Offside Rear Stop lamp remains on when the brakes are released (1.2.1e)**Fail** Nearside Rear Stop lamp remains on when the brakes are released (1.2.1e)**Fail** Centre Rear Stop lamp remains on when the brakes are released (1.2.1e)**MOT #5** 2014-12-10 16:29**MOT test number** 246564844360**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear exhaust corroded**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in offside rear tyre**MOT #4** 2014-12-10 09:37**MOT test number** 585864944331**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear exhaust corroded**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Notice** Nail in offside rear tyre**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2013-12-11 12:46
MOT test number	697025043316
Result	✓ Passed
MOT #2	2012-12-10 17:41
MOT test number	965385742355
Result	✓ Passed
MOT #1	2011-12-12 11:58
MOT test number	629986141301
Result	✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-12-19
Last registration	2020-10-08
Complete history	See info



Registration #1	2008-12-19	25 mi
Registration #2	2011-12-12	27.181 mi
Registration #3	2012-12-10	36.801 mi
Registration #4	2013-12-11	45.801 mi
Registration #5	2014-12-10	57.926 mi
Registration #6	2014-12-10	57.926 mi
Registration #7	2015-10-29	67.666 mi
Registration #8	2015-10-30	67.668 mi
Registration #9	2016-05-20	75.377 mi
Registration #10	2016-05-20	75.377 mi
Registration #11	2016-05-20	75.377 mi
Registration #12	2016-05-20	75.377 mi
Registration #13	2016-05-20	75.377 mi
Registration #14	2016-05-20	75.377 mi
Registration #15	2016-05-20	75.377 mi
Registration #16	2016-05-20	75.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1320 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	5896552