





report date: 2024-03-29

General information

Make	MERCEDES
Model	C C320 CDI SPORT
Colour	Grey
Year of manufacture	2008
Top speed	154 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 1.600 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	27.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.7 mpg
CO2 emission	201 g/km
CO2 label	K



CarCheck.co.uk page 1/13



KN58MYR
report date: 2024-03-29

Internet history

Entry 1

Date	2021-02-02	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/13



KN58MYR
report date: 2024-03-29

MOT history

MOT expiry date	2024-08-15
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	28
Total items failed	2

MOT #13		2023-08-01 13:21
MOT test	number	764933577236
Result		✓ Passed
Next expi	ry date	2024-08-15
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Central Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #12 2022-08-15 15:27 **MOT** test number 372225938294 Result ✓ Passed **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Rear Brake pipe corroded, covered in grease or other material lateral pipe (1.1.11 (c)) Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Cut in n/s/f tyre

MOT #11	2021-08-16 15:26
MOT test	number 291242170581
Result	✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear Brake pipe corroded, covered in grease or other material across axle (1.1.11 (c))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 4/13



report date: 2024-03-29

 MOT #10
 2020-07-30 16:53

 MOT test number
 269058975706

 Result
 ✓ Passed

 MOT #9
 2019-08-03 14:34

 MOT test number
 497586224830

 Result
 ✓ Passed

 Advice
 Brake disc worn, but not excessively front & rear (1.1.14 (a) (i))

MOT #8

MOT test number

743563338060

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #6
 2015-10-26 14:30

 MOT test number
 287641208886

 Result
 ✓ Passed

 MOT #5
 2014-10-23 16:30

 MOT test number
 127916694212

 Result
 ✓ Passed

 Advice
 Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



MOT #4

KN58MYR

report date: 2024-03-29

2013-10-22 11:46

 MOT test number
 587675893233

 Result
 ✓ Passed

 MOT #3
 2012-10-16 11:44

 MOT test number
 926940692205

 Result
 ✓ Passed

 MOT #2
 2012-10-16 11:44

MOT test number 426100192281

Result × Failed

Pass with rectification Nearside Headlamp aim too low (1.8)

Pass with rectification Offside Headlamp aim too low (1.8)

MOT #1 2011-10-21 11:52

MOT test number 918064791210

Result ✓ Passed

CarCheck.co.uk page 6/13



KN58MYR
report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13




report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Type

Category

Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

Plate changes	More info >
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	OK STE
Plate since	
Current registration	UK SIR
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-10-20
Last registration	2023-08-01
Complete history	See info



Registration #1	2008-10-20	18 mi
Registration #2	2011-10-21	32.510 mi
Registration #3	2012-10-16	42.218 mi
Registration #4	2013-10-22	51.825 mi
Registration #5	2014-10-23	56.501 mi
Registration #6	2015-10-26	71.642 mi
Registration #7	2016-12-14	90.232 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		D.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



report date: 2024-03-29

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1447 mm
Length	4581 mm
Wheel base	2715 mm
Kerb weight	1555 kg
Max. allowed weight	2185 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64296040776265

CarCheck.co.uk page 13/13