




report date: 2024-03-29

General information

Make	JAGUAR
Model	XJ TDVI SOVEREIGN LWB
Colour	Black
Year of manufacture	2007
Top speed	140 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	204 BHP
Max. torque	435 Nm at 1.900 rpm
Engine capacity	2.720 cc
Cylinders	6
Fuel type	Diesel
Consumption city	26.2 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.9 mpg
CO2 emission	214 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-09-28
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-27
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	27
Total items failed	5

MOT #17	2023-12-28 09:44
MOT test number	209766713542
Result	✓ Passed
Next expiry date	2024-12-27
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge at limit (5.2.3 (e))
Minor	Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Power steering component has slight seepage from a component steering rack pinion seal (2.1.5 (a))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Outer bush gaiter split
Minor	Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Minor	Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16**

2023-12-28 09:44

**MOT test number**

942842877225

**Result****✗ Failed****Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Minor** Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Minor** Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Power steering component has slight seepage from a component steering rack pinion seal (2.1.5 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge at limit (5.2.3 (e))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Outer bush gaiter split**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #15**

2022-08-16 09:56

**MOT test number**

205419208319

**Result****✓ Passed****MOT #14**

2021-09-24 12:22

**MOT test number**

329901760467

**Result****✓ Passed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2019-12-21 10:19**MOT test number** 686826452261**Result** ✓ Passed**Advice** Brake fluid slightly dark**Advice** Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))**MOT #12** 2019-12-20 12:10**MOT test number** 795426343933**Result** ✗ Failed**Advice** Brake fluid slightly dark**Advice** Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))**Fail** Nearside Rear Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))**MOT #11** 2018-12-13 17:04**MOT test number** 738402982973**Result** ✓ Passed**MOT #10** 2018-12-12 13:29**MOT test number** 183771784019**Result** ✗ Failed**Fail** Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #9** 2017-11-20 10:09**MOT test number** 980666845495**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit and rear (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit and rear (4.1.E.1)

**MOT #8** 2016-12-12 16:46**MOT test number** 175164493253**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit and offside rear (4.1.E.1)**MOT #7** 2015-11-28 09:04**MOT test number** 239655119829**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit BOTH INNER EDGES (4.1.E.1)**MOT #6** 2014-12-27 09:34**MOT test number** 945021964329**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-01-31 10:04**MOT test number** 617011934015**Result** ✓ Passed**MOT #4** 2013-02-25 10:51**MOT test number** 549436753077**Result** ✓ Passed**MOT #3** 2012-03-01 10:34**MOT test number** 586391562096**Result** ✓ Passed



MOT #2	2011-03-02 16:08
MOT test number	659221961009
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2010-01-11 09:46
MOT test number	180921510025
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
27 December 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	27 December 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history


Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>BL56AXW</b>
Plate since	2024-03-29
Current registration	<b>BL56AXW</b>
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-01-16
Last registration	2023-12-28
Complete history	<a href="#">See info</a>



Registration #1	2007-01-16	29 mi
Registration #2	2010-01-11	19.100 mi
Registration #3	2011-03-02	21.147 mi
Registration #4	2012-03-01	23.160 mi
Registration #5	2013-02-25	24.177 mi
Registration #6	2014-12-27	28.557 mi
Registration #7	2015-11-28	29.281 mi
Registration #8	2016-12-12	30.949 mi
Registration #9	2017-11-20	31.973 mi
Registration #10	2018-05-20	32.377 mi
Registration #11	2019-05-20	32.377 mi
Registration #12	2020-05-20	32.377 mi
Registration #13	2021-05-20	32.377 mi
Registration #14	2022-05-20	32.377 mi
Registration #15	2023-05-20	32.377 mi
Registration #16	2024-05-20	32.377 mi
Registration #17	2025-05-20	32.377 mi
Registration #18	2026-05-20	32.377 mi

More info >



Dimensions & weight

Width	1898 mm
Height	1455 mm
Length	5215 mm
Wheel base	3159 mm
Kerb weight	1659 kg
Max. allowed weight	2306 kg

Additional information

Fuel tank capacity	85 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	02230647G