




report date: 2024-11-08

General information

Make	MINI
Model	COOPER D LONDON 2012 EDITION
Colour	Red
Year of manufacture	2012
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-06-26
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-08-20
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	18
Total items failed	10

MOT #13 2024-08-21 11:14

MOT test number 123895156747

Result ✓ Passed

Next expiry date 2025-08-20

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #12 2023-01-21 12:36

MOT test number 998942211706

Result ✓ Passed

Advice Rear sub frame corroded

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Clutch pipe corroded

MOT #11 2022-01-24 12:29

MOT test number 568875845712

Result ✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Clutch pipe corroded



MOT #10 2022-01-21 09:50

MOT test number 334088440712

Result ✗ Failed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Offside Rear Inner Road wheel fractured (5.2.2 (a))
- Advice** Clutch pipe corroded

MOT #9 2021-01-22 08:57

MOT test number 614563343500

Result ✓ Passed

MOT #8 2019-07-10 08:01

MOT test number 486221272754

Result ✓ Passed

MOT #7 2018-07-03 14:35

MOT test number 767392306102

Result ✓ Passed

- Advice** Wipers slightly smearing
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #6 2018-06-30 09:25

MOT test number 836021469706

Result ✗ Failed

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Wipers slightly smearing



MOT #5	2017-07-10 13:45
MOT test number	821581153138
Result	✓ Passed
Advice	Nearside Rear brake disc outer surface has a corroded lip

MOT #4	2017-07-07 10:41
MOT test number	531014712709
Result	✗ Failed
Fail	Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
Advice	Nearside Rear brake disc outer surface has a corroded lip
Fail	Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
Fail	Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)
Fail	Nearside Front Road wheel cracked 2 places (4.2.A.1a)

MOT #3	2016-06-30 09:16
MOT test number	465431629725
Result	✓ Passed
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)
Advice	Offside Front tyres worn smooth on inner edge



MOT #2 2016-06-30 08:34

MOT test number 228262915023

Result ✗ Failed

Fail Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Front tyres worn smooth on inner edge

Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)

Fail Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #1 2015-06-20 09:19

MOT test number 879161575155

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
20 August 2025

Tax status	Valid until 1 January
Days left	23
MOT expiry date	20 August 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	AX12DNV
Plate since	2019-09-29
Current registration	AX12DNV
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-06-29
Last registration	2024-08-21
Complete history	See info



Registration #1	2012-06-29	25 mi
Registration #2	2015-06-20	44.315 mi
Registration #3	2016-06-30	66.299 mi
Registration #4	2016-06-30	66.299 mi
Registration #5	2017-07-07	79.545 mi
Registration #6	2017-07-10	79.545 mi
Registration #7	2018-06-30	92.263 mi
Registration #8	2018-07-03	92.399 mi
Registration #9	2019-06-30	92.399 mi
Registration #10	2019-06-30	92.399 mi
Registration #11	2019-06-30	92.399 mi
Registration #12	2019-06-30	92.399 mi
Registration #13	2019-06-30	92.399 mi
Registration #14	2019-06-30	92.399 mi
Registration #15	2019-06-30	92.399 mi

[More info >](#)



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	70058141