





report date: 2024-03-28

# General information

Make	VOLVO	
Model	XC90 RDESGN PRO T8 RCHRG AWD A	
Colour	Black	
Year of manufacture	2021	
Gearbox	-	

# Engine & fuel consumption

Engine capacity	1.969 сс
Fuel type	Hybrid / Electric
CO2 emission	70 g/km
CO2 label	A



CarCheck.co.uk page 1/10



KW210YB

report date: 2024-03-28

# Internet history

### Entry 3

Date 2022-01-09

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

### Entry 2

Date	2021-11-14	
Pictures	0	
Listing price	View report	

### source: heycar.co.uk

## Entry 1

Date	2021-11-11	
Pictures	5	
Listing price	View report	









source: cargurus.co.uk

CarCheck.co.uk page 2/10



MOT history

MOT expiry date	2025-03-25
MOT pass rate	50 %
MOT passed	1
Failed MOT tests	1
Total advice items	6
Total items failed	0

MOT #2		2024-03-21 10:05
MOT test	number	215040819747
Result		✓ Passed
Next expiry date 2025-03-2		2025-03-25
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		

MOT #1		2024-03-20 11:27
MOT test	number	800669199015
Result		<b>×</b> Failed
MAJOR	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	
<b>MAJOR</b> Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Outer wall (5.2.3 (d) (i))		
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cord	ds (5.2.3 (d) (i))

CarCheck.co.uk page 3/10



# Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	25 March 2025
Full MOT history	See MOT history

# Tax calculation

CarCheck.co.uk page 4/10



KW210YB

report date: 2024-03-28

# Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



factor scincol

KW210YB

report date: 2024-03-28

More info >

# For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this VOLVO had different number plates.

CarCheck.co.uk page 7/10



## Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 8/10



KW210YB

report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2021-03-26
Last registration	2024-03-21
Complete history	See info



Registration #1	2021-03-26	16 mi
Registration #2		77,777 66
Registration #3		11.777 es
Registration #4		71.777 66
Registration #5		9.77 sc
Pogistration #6		

Registration #6

More info >

CarCheck.co.uk page 9/10



Car features

S0225	Air conditioning
50295	
50482	
60501	
50566	
60567	
50569	

# Additional information

CarCheck.co.uk page 10/10