





report date: 2024-03-29

General information

Make	FORD
Model	MUSTANG
Colour	Grey
Year of manufacture	2005
Gearbox	-

Engine & fuel consumption

Engine capacity	4.601 cc
Fuel type	Petrol



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



RLO5WTE report date: 2024-03-29

MOT history

MOT expiry date	2025-03-23
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	2
Total items failed	4

MOT #20	2024-03-20 17:21
MOT test number	519250972666
Result	✓ Passed
Next expiry date	2025-03-23

MOT #19	2023-03-13 11:07
MOT test number	421734369070
Result	✓ Passed

MOT #18	2022-03-14 10:34
MOT test number	479318101138
Result	✓ Passed

MOT #17		2022-03-14 10:34
MOT test number		776100287170
Result		× Failed
Pass with rectification	Offside Headlamp not working on main beam (4.1.1 (a) (ii))	

MOT #16	2021-03-05 12:00
MOT test number	525847447798
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #15	2020-03-07 10:16
MOT test number	296392701111
Result	✓ Passed
MOT #14	2019-03-04 14:07
MOT test number	379480028328
Result	✓ Passed
MOT #13	2018-03-24 10:19
MOT test number	681940530660
Result	✓ Passed
MOT #12	2017-05-06 09:18
MOT test number	986946216700
Result	✓ Passed
NOT #11	2016 05 21 14.52
MOT #11 MOT test number	2016-05-31 14:53 714197095553
Result	
Result	✓ Passed
MOT #10	2015-06-13 09:25
MOT test number	105714865117
Result	✓ Passed
MOT #9	
1101 #3	2014-07-10 10:13
MOT test number	2014-07-10 10:13 945081894138
MOT test number	945081894138
MOT test number	945081894138
MOT test number Result	945081894138 ✓ Passed
MOT test number Result MOT #8	945081894138 Passed 2013-08-19 10:17

CarCheck.co.uk page 4/13



Result

RL05WTE

report date: 2024-03-29

× Failed

MOT #7 2012-08-21 11:28

MOT test number 526904532217

Result Passed

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #6 2012-08-21 11:28

MOT test number 129054832260

Pass with rectification Nearside Headlamp aim too high (1.8)

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #5 2011-08-19 10:03

MOT test number 519681031279

Result ✓ Passed

MOT #4 2011-08-10 09:29

MOT test number 149422021218

Result X Failed

Fail Offside Brake cable has restricted free movement (3.5.1k)

Fail Parking brake: efficiency below requirements (3.7.C.1b)

MOT #3 2010-08-26 13:48

MOT test number 122788030212

MOT #2 2009-09-04 13:58

MOT test number 492827349202

Result \rightarrow Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1 2008-07-10 14:09

MOT test number 734612298105


Result ✓ Passed

CarCheck.co.uk page 6/13



RLO5WTE report date: 2024-03-29

Tax & MOT check



Days left 94

MOT expiry date 23 March 2025

Full MOT history See MOT history

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



RLO5WTE report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-07-04
Last registration	2024-03-20
Complete history	See info



Registration #1	2005-07-04	10 mi
Registration #2	2008-07-10	18.807 mi
Registration #3	2009-09-04	22.864 mi
Registration #4	2010-08-26	26.306 mi
Registration #5	2011-08-10	27.903 mi
Registration #6	2011-08-19	27.907 mi
Registration #7	2012-08-21	29.413 mi
Registration #8	2013-08-19	31.082 mi
Registration #9	2014-07-10	31.857 mi
Registration #10	2015-06-13	34.817 mi
Registration #11	2016-05-31	37.544 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 au
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.117 au
Registration #19		11.777 mi
Registration #20		D.777 es
Registration #21		11.777 46

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Additional information

Number of seats	5
Engine number	5193237

CarCheck.co.uk page 13/13