



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D R-DESIGN SE
Colour	Black
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-16
Pictures	36
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-09-21
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	28
Total items failed	10

MOT #17	2023-09-13 15:55
MOT test number	314693597100
Result	✓ Passed
Next expiry date	2024-09-21
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #16	2023-09-13 10:26
MOT test number	468897070902
Result	✗ Failed
Fail	Offside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #15	2022-09-12 08:22
MOT test number	698515522007
Result	✓ Passed

MOT #14	2021-09-22 13:35
MOT test number	864440960317
Result	✓ Passed

**MOT #13** 2021-02-26 16:29**MOT test number** 468823144844**Result** ✓ Passed**MOT #12** 2021-02-24 10:38**MOT test number** 723079289342**Result** ✗ Failed**Fail** Nearside Front Service brake excessively binding (1.2.1 (f))**MOT #11** 2020-03-05 14:32**MOT test number** 498308267380**Result** ✓ Passed**MOT #10** 2019-03-20 08:57**MOT test number** 948554917444**Result** ✓ Passed**Advice** Coil spring corroded All (5.3.1 (b) (i))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #9** 2019-03-19 14:12**MOT test number** 642130354996**Result** ✗ Failed**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Coil spring corroded All (5.3.1 (b) (i))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #8** 2018-03-23 14:55**MOT test number** 978174385189**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Rear tyres going out of shape on inner edges**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #7** 2018-03-23 10:22**MOT test number** 386822104327**Result** ✗ Failed**Advice** Rear tyres going out of shape on inner edges**Fail** Offside Front Valve stem seriously damaged (4.1.D.1e)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Front tyres wearing on inner edges**Fail** Nearside Front Valve stem seriously damaged (4.1.D.1e)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #6** 2017-03-14 13:50**MOT test number** 217215682189**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside rear tyre worn inside edge**MOT #5** 2017-03-14 13:50**MOT test number** 420832603194**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside rear tyre worn inside edge**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #4** 2016-03-29 16:02**MOT test number** 514906519963**Result** ✓ Passed**Advice** Engine cover & under-trays fitted**MOT #3** 2015-03-09 11:38**MOT test number** 106618065407**Result** ✓ Passed



MOT #2	2014-03-12 16:10
MOT test number	387611274052
Result	✓ Passed

MOT #1	2013-02-25 13:40
MOT test number	249926953027
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
21 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	21 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>YX10UZW</b>
Plate since	2019-09-28
Current registration	<b>YX10UZW</b>
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-02
Last registration	2023-09-13
Complete history	<a href="#">See info</a>



Registration #1	2010-03-02	16 mi
Registration #2	2013-02-25	25.741 mi
Registration #3	2014-03-12	37.347 mi
Registration #4	2015-03-09	47.525 mi
Registration #5	2016-03-29	58.657 mi
Registration #6	2017-03-14	68.885 mi
Registration #7	2017-03-14	68.885 mi
Registration #8	2018-03-23	80.109 mi
Registration #9	2018-03-23	80.109 mi
Registration #10	2019-03-19	90.847 mi
Registration #11	2019-03-20	90.847 mi
Registration #12	2019-03-20	90.847 mi
Registration #13	2019-03-20	90.847 mi
Registration #14	2019-03-20	90.847 mi
Registration #15	2019-03-20	90.847 mi
Registration #16	2019-03-20	90.847 mi
Registration #17	2019-03-20	90.847 mi
Registration #18	2019-03-20	90.847 mi
Registration #19	2019-03-20	90.847 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1737 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	672615
---------------	--------