



report date: 2024-03-29

General information

Make	CITROEN
Model	C5 HDI VTR PLUS NAV
Colour	Black
Year of manufacture	2010
Top speed	129 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	160 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-04-13
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-08
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	34
Total items failed	14

MOT #15	2023-08-25 08:45
MOT test number	860321105312
Result	✓ Passed
Next expiry date	2024-09-08

MOT #14	2023-08-24 15:53
MOT test number	726516404917
Result	✗ Failed
Fail	Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #13	2022-09-09 07:34
MOT test number	657765348470
Result	✓ Passed

**MOT #12**

2022-09-08 12:18

MOT test number

547315187254

Result**✗ Failed****Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Anti-roll bar ball joint excessively worn drop link (5.3.4 (a) (i))**MOT #11**

2021-12-10 11:59

MOT test number

652051094987

Result**✗ Failed****Fail** Front Windscreen washer not working (3.5 (a))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play drop link (5.3.4 (a) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play drop link (5.3.4 (a) (i))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Power steering ram leaking steering rack (2.1.5 (a))

**MOT #10**

2020-12-17 13:08

MOT test number

553280474176

Result

✓ Passed

- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge near wear limit and very worn on inner edge (5.2.3 (e))
- Advice** Power steering component has slight seepage from a component (2.1.5 (a))
- Advice** Under trays fitted not allowing inspection of some underside components
- Advice** Offside Front Tyre worn close to legal limit/worn on edge near wear limit and very worn on inner edge (5.2.3 (e))

MOT #9

2020-12-10 09:58

MOT test number

445206378588

Result

✗ Failed

- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Under trays fitted not allowing inspection of some underside components
- Advice** Offside Front Tyre worn close to legal limit/worn on edge near wear limit and very worn on inner edge (5.2.3 (e))
- Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Power steering component has slight seepage from a component (2.1.5 (a))
- Fail** Nearside Front Suspension unit leaking (5.3.5 (c))
- Advice** Exhaust heat shield insecure
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge near wear limit and very worn on inner edge (5.2.3 (e))
- Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #8** 2019-12-13 15:21**MOT test number** 507662782980**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge Very worn on inside edge (5.2.3 (e))**Advice** Rear Suspension pipe damaged but not to excess Corroded (5.3.5 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn on inside edge (5.2.3 (e))**Advice** Hydraulic leak, but not excessive (8.4.1 (a) (i))**MOT #7** 2019-12-12 09:47**MOT test number** 606613793724**Result** ✗ Failed**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Very worn on inside edge (5.2.3 (e))**Advice** Rear Suspension pipe damaged but not to excess Corroded (5.3.5 (b) (i))**Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn on inside edge (5.2.3 (e))**Advice** Hydraulic leak, but not excessive (8.4.1 (a) (i))**MOT #6** 2018-12-10 08:54**MOT test number** 275320404511**Result** ✓ Passed

**MOT #5** 2018-01-12 09:48**MOT test number** 922639969445**Result** ✓ Passed**Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Power steering component(s) has slight seepage from a component (2.3.3b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2017-01-16 10:47**MOT test number** 612234707091**Result** ✓ Passed**MOT #3** 2016-01-14 09:53**MOT test number** 684482595199**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2015-01-19 10:54**MOT test number** 176969415440**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2014-01-13 11:42**MOT test number** 525363614049**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
8 September 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	8 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	VE60BBJ
Plate since	2019-03-29
Current registration	VE60BBJ
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-11-30
Last registration	2023-08-25
Complete history	See info



Registration #1	2010-11-30	18 mi
Registration #2	2014-01-13	26.682 mi
Registration #3	2015-01-19	29.218 mi
Registration #4	2016-01-14	32.328 mi
Registration #5	2017-01-16	36.440 mi
Registration #6	2018-01-12	40.512 mi
Registration #7	2018-12-10	45.808 mi
Registration #8	2019-12-12	50.776 mi
Registration #9	2019-12-13	50.776 mi
Registration #10	2020-01-20	51.277 mi
Registration #11	2020-01-20	51.277 mi
Registration #12	2020-01-20	51.277 mi
Registration #13	2020-01-20	51.277 mi
Registration #14	2020-01-20	51.277 mi
Registration #15	2020-01-20	51.277 mi
Registration #16	2020-01-20	51.277 mi
Registration #17	2020-01-20	51.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	81%
Children	77%
Pedestrian	32%
Safety systems	83%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1479 mm
Length	4289 mm
Wheel base	2815 mm
Kerb weight	1595 kg
Max. allowed weight	2286 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYWT4004886