

Ford



### General information

Make	FORD
Model	GALAXY GHIA TDCI
Colour	Silver
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	159 g/km
CO2 label	G







# Internet history

Entry 1	
Date	2021-08-15
Pictures	12

Listing price

View report



source: cargurus.co.uk



# MOT history

MOT expiry date	2025-03-31
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	47
Total items failed	1

MOT #16	2024-03-27 11:11
MOT test number	133248103670
Result	✓ Passed
Next expiry date	2025-03-31
Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriora	ated (5.3.4 (b) (i))
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	)
Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly (5.1.2 (b) (i))	worn Trailing arm bush
Advice Heavy oil contamination to underside of vehicle	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b)	))
Advice Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightl (5.1.2 (b) (i))	y worn Trailing arm bush
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #15	2023-03-22 10:43
MOT test number	683221865168
Result	✓ Passed
Minor Offside Front Anti-roll bar linkage ball joint dus	cover severely deteriorated (5.3.4 (b) (i))
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)	
<b>Minor</b> Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))	





MOT #14	2022-03-28 10:09	
MOT test number	933787151280	
Result	✓ Passed	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
MOT #13	2021-03-09 13:55	
MOT test number	612348695815	
Result	✓ Passed	
Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
<b>Minor</b> Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))		
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

MOT #12		2021-03-06 16:26
MOT test	number	675890587603
Result		🗙 Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MAJOR	Central Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))		



<b>BN09GYA</b>
report date: 2024-03-29

MOT #11	2020-03-25 12:09
MOT test number	289983181618
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive r (5.3.4 (a) (i))	novement trailing
Advice Nearside Rear Lower Suspension arm pin or bush worn but not resulting in exce (5.3.4 (a) (i))	essive movement
Advice Items removed from driver's view prior to test	
Advice Front screen damaged on nearside	
Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive mo (5.3.4 (a) (i))	ovement trailing
Advice Vehicles internal headlight adjuster altered to recheck lights	
Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in excess (5.3.4 (a) (i))	sive movement
Advice Engine cover & under-shield fitted	



BN09GYA report date: 2024-03-29

MOT #10		2020-03-23 15:42
MOT test	number	218644168291
Result		🗙 Failed
MAJOR	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	
Advice	Items removed from driver's view prior to test	
Pass wit	h rectification Offside Headlamp insecure (4.1.1 (c))	
Advice	Front screen damaged on nearside	
<b>Advice</b> (5.3.4 (a)	Offside Rear Suspension arm pin or bush worn but not resulting in excessive mo (i))	vement trailing
DANGER	OUS Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
<b>Advice</b> (5.3.4 (a)	Offside Rear Lower Suspension arm pin or bush worn but not resulting in excess i))	ive movement
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Vehicles internal headlight adjuster altered to recheck lights	
<b>Advice</b> (5.3.4 (a)	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive m i))	novement trailing
Advice	Engine cover & under-shield fitted	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
<b>Advice</b> (5.3.4 (a)	Nearside Rear Lower Suspension arm pin or bush worn but not resulting in exces i))	ssive movement

МОТ #9	2019-03-29 09:21
MOT test number	508367810675
Result	✓ Passed
MOT #8	2019-03-28 17:38

MOT test	number	926068956863
Result		🗙 Failed
MAJOR	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	





MOT #7	2018-03-26 15:23
MOT test number	722989686559
Result	✓ Passed
МОТ #6	2017-03-13 16:05
MOT test number	580735256496
Result	✓ Passed

MOT #5		2016-03-29 14:21
MOT test	number	199715426169
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Centre Rear CHILD SEAT FITTED	
Advice	Nearside Rear CHILD SEAT FITTED	
Advice	Offside Rear CHILD SEAT FITTED	

MOT #4	2015-03-30 16:50
MOT test number	179899485093
Result	✓ Passed
MOT #3	2014-03-28 14:11
MOT test number	466217584083
Result	✓ Passed
MOT #2	2013-03-14 16:18
MOT test number	279313373064

Result

🗸 Passed





MOT #1	2012-03-07 10:02
MOT test number	206517962066
Result	✓ Passed



BN09GYA report date: 2024-03-29

Tax & MOT check

√ Taxed	√ МОТ
Tax due: 1 March 2025	Expires: 31 March 2025
Tax status	Valid until 1 March
Days left	306
MOT expiry date	31 March 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
********	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



BN09GYA report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-03-31
Last registration	2024-03-27
Complete history	See info



Registration #1	2009-03-31	6 mi
Registration #2	2012-03-07	34.931 mi
Registration #3	2013-03-14	42.804 mi
Registration #4	2014-03-28	50.116 mi
Registration #5	2015-03-30	577.555 mi
Registration #6	2016-03-29	67.506 mi
Registration #7	2017-03-13	75.897 mi
Registration #8	2018-03-26	84.999 mi
Registration #9	2019-03-28	95.154 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 est
Registration #18		11.117 est





#### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 15/15

Number of axles	2
Engine number	9K79192