





report date: 2024-03-28

General information

| Make | VOLVO |
|---------------------|----------------------|
| Model | V50 D DRIVE R-DESIGN |
| Colour | Grey |
| Year of manufacture | 2010 |
| Top speed | 118 mph |
| 0 - 60 mph | 10.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 109 BHP |
|-------------------------|---------------------|
| Max. torque | 240 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 49.6 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 62.8 mpg |
| CO2 emission | 119 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/12



Internet history

| Fn | trv | 1 |
|----|-------|---|
| | ILI Y | - |

| LIICI Y I | |
|---------------|-------------|
| Date | 2021-12-18 |
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2024-12-10 |
|--------------------|------------|
| MOT pass rate | 92 % |
| MOT passed | 12 |
| Failed MOT tests | 1 |
| Total advice items | 11 |
| Total items failed | 1 |

| MOT #13 | 2023-11-28 11:19 |
|------------------|------------------|
| MOT test number | 919355212672 |
| Result | ✓ Passed |
| Next expiry date | 2024-12-10 |

| MOT #12 | 2022-12-06 10:38 |
|-----------------|------------------|
| MOT test number | 205608670213 |
| Result | √ Passed |

| MOT #11 | 2021-11-23 16:44 |
|--|--|
| MOT test number | 324872604987 |
| Result | ✓ Passed |
| Minor Registration plate lamp inoperative in the case of multipl | e lamps or light sources (4.7.1 (b) (i)) |
| Advice Offside Rear Tyre cracked and perished | |

| MOT #10 | 2020-12-04 16:12 |
|-----------------|------------------|
| MOT test number | 252527223048 |
| Result | ✓ Passed |
| | |

| MOT #9 | 2019-12-10 13:52 |
|-----------------|------------------|
| MOT test number | 375428060506 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/12



MOT #8 2018-12-11 16:15

MOT test number 282827984376

MOT #7 2018-02-28 16:05

MOT test number 588619139136

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2018-02-28 09:09

MOT test number 305757138717

Result X Failed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front coil spring broken (2.4.C.1a)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2017-02-27 09:05

MOT test number 596619747431

Result
✓ Passed

MOT #4 2016-02-23 11:12

MOT test number 397686365623

CarCheck.co.uk page 4/12



MOT #3

MOT test number

Result

Notice Front tyres worn on edges

2015-02-27 11:24

✓ Passed

| Notice Front tyres worn on edges | |
|----------------------------------|------------------|
| MOT #2 | 2014-02-25 08:50 |
| MOT test number | 109016154412 |
| Result | ✓ Passed |
| MOT #1 | 2013-03-13 09:05 |
| MOT test number | 616482573020 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 155 |
| MOT expiry date | 10 December 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| Owner mistory | |
|--|-------------|
| For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full | |
| | |
| | |
| | |
| | |
| THE STATE OF THE S | |
| | |
| *************************************** | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | |
| Current registration | NIP. UK |
| Plate since | |
| Current registration | NK NK |
| Plate since | |
| | More info > |
| | |
| | |

CarCheck.co.uk page 9/12



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 15 |
| First mileage registration | 2010-03-26 |
| Last registration | 2023-11-28 |
| Complete history | See info |



| Registration #1 | 2010-03-26 | 25 mi |
|------------------|------------|-----------|
| Registration #2 | 2013-03-13 | 22.647 mi |
| Registration #3 | 2014-02-25 | 29.038 mi |
| Registration #4 | 2015-02-27 | 36.548 mi |
| Registration #5 | 2016-02-23 | 46.147 mi |
| Registration #6 | 2017-02-27 | 56.368 mi |
| Registration #7 | 2018-02-28 | 66.836 mi |
| Registration #8 | 2018-02-28 | 66.839 mi |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | D.277 es |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 91% |
| Children | 78% |
| Pedestrian | 26% |
| Safety systems | 71% |
| Overall rating | 73% |
| Video | see crash video |



Dimensions & weight

| Width | 1770 mm |
|---------------------|---------|
| Height | 1457 mm |
| Length | 4522 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1442 kg |
| Max. allowed weight | 1900 kg |

Additional information

| Fuel tank capacity | 52 l | |
|-----------------------------------|------------------|-----------|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 5 p | age 12/12 |

Number of axles2Engine number957553