



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY
Colour	Silver
Year of manufacture	2014
Top speed	121 mph
0 - 100 km/h	10.2 seconds
Gearbox	6 speed manual

Engine & fuel consumption

Power	103 kW / 140 HP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	50.0 mpg
Consumption combined	44.4 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-22
Pictures	15
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-26
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	33
Total items failed	7

MOT #11	2023-07-04 07:57
MOT test number	684591717255
Result	✓ Passed
Next expiry date	2024-07-26
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge On limit of 1.6mm/uneven wear inner edge (5.2.3 (e))

MOT #10	2022-07-19 09:42
MOT test number	278357166629
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2mm and edges worn (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 3mm and edges worn (5.2.3 (e))

MOT #9	2021-07-27 16:13
MOT test number	448874554162
Result	✓ Passed

**MOT #8**

2020-10-21 07:36

MOT test number

862095567293

Result

✓ Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7**

2020-10-20 09:30

MOT test number

897244872029

Result

✗ Failed

Advice Nearside Rear Nail in tyre**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2.40mm (5.2.3 (e))**MOT #6**

2019-10-19 08:42

MOT test number

950319797642

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge 1.80mm (5.2.3 (e))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #5** 2019-10-19 08:42**MOT test number** 817094813757**Result** ✗ Failed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 1.80mm (5.2.3 (e))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**MOT #4** 2018-10-19 08:45**MOT test number** 764029049946**Result** ✓ Passed**Advice** Engine & under covers fitted to vehicle.**Advice** Nearside Front Tyre worn inner edge.**MOT #3** 2018-10-18 13:32**MOT test number** 229098307611**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Tyre worn inner edge.**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 1.70mm (5.2.3 (e))**Advice** Engine & under covers fitted to vehicle.

**MOT #2** 2017-10-20 14:29**MOT test number** 169523558754**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Engine & under covers fitted to vehicle.**Advice** Nearside Rear Tyre worn close to the legal limit 2.40mm (4.1.E.1)**MOT #1** 2017-10-20 09:27**MOT test number** 128832660303**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened Both (3.5.1i)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Engine & under covers fitted to vehicle.**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Fail** Offside Front front brake excessively fluctuating (3.7.B.3)**Advice** Nearside Rear Tyre worn close to the legal limit 2.40mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
26 July 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	26 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-10-22
Last registration	2023-07-04
Complete history	See info



Registration #1	2014-10-22	26 mi
Registration #2	2017-10-20	22.323 mi
Registration #3	2017-10-20	22.323 mi
Registration #4	2018-10-18	28.506 mi
Registration #5	2018-10-19	28.506 mi
Registration #6	2019-10-19	33.534 mi
Registration #7	2019-10-19	33.534 mi
Registration #8	2019-10-19	33.534 mi
Registration #9	2019-10-19	33.534 mi
Registration #10	2019-10-19	33.534 mi
Registration #11	2019-10-19	33.534 mi
Registration #12	2019-10-19	33.534 mi
Registration #13	2019-10-19	33.534 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1590 kg

Additional information

Fuel tank capacity	70 l
Number of axles	2
Engine number	EA09685