



report date: 2024-03-29

General information

Make	SUZUKI
Model	SX4 GLX
Colour	Orange
Year of manufacture	2007
Top speed	112 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	165 g/km
CO2 label	G





## MOT history

MOT expiry date	2021-07-30
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	11
Total items failed	4

MOT #14 2020-07-31 08:05

MOT test number 475997146893

Result ✓ Passed

Next expiry date 2021-07-30

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13 2019-08-27 07:08

MOT test number 557669487685

Result ✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2018-08-31 07:17**MOT test number** 729772461793**Result** ✓ Passed

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

**MOT #11** 2017-08-26 09:51**MOT test number** 514896261202**Result** ✓ Passed**MOT #10** 2017-08-26 09:51**MOT test number** 753399265995**Result** ✗ Failed

**Pass with rectification** Offside Front coil spring broken (2.4.C.1a)

**Pass with rectification** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #9** 2016-08-16 15:59**MOT test number** 857616152670**Result** ✓ Passed**MOT #8** 2016-08-16 10:40**MOT test number** 322620075162**Result** ✗ Failed

**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

**MOT #7** 2015-08-25 09:27**MOT test number** 796474166615**Result** ✓ Passed**Advice** Front lower arm, inner bushes starting to split very slightly.**MOT #6** 2014-08-26 15:47**MOT test number** 155368734242**Result** ✓ Passed**MOT #5** 2014-08-26 12:14**MOT test number** 466708034206**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #4** 2013-08-20 10:28**MOT test number** 408682133265**Result** ✓ Passed**MOT #3** 2012-08-28 14:38**MOT test number** 547211942287**Result** ✓ Passed**Notice** Both rear tyres worn to 3mm**MOT #2** 2011-08-15 08:40**MOT test number** 966467221276**Result** ✓ Passed**MOT #1** 2010-08-13 08:38**MOT test number** 592495320247**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
1 February 2021

X

MOT

Expired:  
30 July 2021

Tax status	Expired at 1 February 2021
Days left	1183 days too late
MOT expiry date	30 July 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>YX57OMW</b>
Plate since	2019-09-29
Current registration	<b>YX57OMW</b>
Plate since	2019-09-29

More info >





Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-09-01
Last registration	2020-07-31
Complete history	<a href="#">See info</a>



Registration #1	2007-09-01	24 mi
Registration #2	2010-08-13	6.587 mi
Registration #3	2011-08-15	11.286 mi
Registration #4	2012-08-28	16.380 mi
Registration #5	2013-08-20	21.105 mi
Registration #6	2014-08-26	27.630 mi
Registration #7	2014-08-26	27.630 mi
Registration #8	2015-08-25	33.696 mi
Registration #9	2016-08-25	39.762 mi
Registration #10	2017-08-25	45.828 mi
Registration #11	2018-08-25	51.894 mi
Registration #12	2019-08-25	57.960 mi
Registration #13	2020-07-31	64.026 mi
Registration #14	2021-07-31	70.092 mi
Registration #15	2022-07-31	76.158 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1755 mm
Height	1605 mm
Length	4235 mm
Wheel base	2500 mm
Kerb weight	1205 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1177270