



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D3 SE
Colour	Blue
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.9 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-10-12
Pictures	0
Listing price	View report

source: autotrader.co.uk

Entry 1

Date	2021-07-26
Pictures	19
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-16
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	25
Total items failed	0

MOT #16	2024-03-01 13:34
MOT test number	597992293711
Result	✓ Passed
Next expiry date	2025-03-16
Minor	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #15	2024-03-01 12:08
MOT test number	604304103296
Result	✗ Failed
DANGEROUS	Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
DANGEROUS	Nearside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))

MOT #14	2023-03-17 14:28
MOT test number	240774946157
Result	✓ Passed
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #13** 2023-03-17 12:43**MOT test number** 682764257339**Result** ✗ Failed**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Rear Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #12** 2022-05-24 13:34**MOT test number** 592378889405**Result** ✓ Passed**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11** 2021-07-19 14:48**MOT test number** 541506395828**Result** ✓ Passed**MOT #10** 2020-11-17 12:32**MOT test number** 790151624872**Result** ✓ Passed

**MOT #9** 2020-11-16 16:47**MOT test number** 849328431570**Result** ✗ Failed

DANGEROUS Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure nail in side and run on flat (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #8 2019-05-13 13:29**MOT test number** 118849389236**Result** ✓ Passed

Advice Advise both rear tyres tread worn uneven

Advice Advise both rear indicators pale

MOT #7 2019-05-13 11:48**MOT test number** 811640441656**Result** ✗ Failed

MAJOR Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Advise both rear tyres tread worn uneven

Advice Advise both rear indicators pale

MOT #6 2018-05-02 09:27**MOT test number** 840160897560**Result** ✓ Passed**MOT #5** 2017-05-04 15:28**MOT test number** 336780228218**Result** ✓ Passed



MOT #4	2016-05-18 09:55
MOT test number	332474255663
Result	✓ Passed
Advice	Front Brake lining(s) wearing thin (3.5.1g)
Advice	Rear Brake lining(s) wearing thin (3.5.1g)

MOT #3	2015-05-19 11:04
MOT test number	538669435126
Result	✓ Passed

MOT #2	2014-09-29 14:40
MOT test number	317732374214
Result	✓ Passed

MOT #1	2013-09-25 13:59
MOT test number	397148863258
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
16 March 2025

Tax status	Valid until 1 October
Days left	155
MOT expiry date	16 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2023-03-29
Current registration	XXXXXX
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-10-29
Last registration	2024-03-01
Complete history	See info



Registration #1	2010-10-29	18 mi
Registration #2	2013-09-25	32.564 mi
Registration #3	2014-09-29	42.441 mi
Registration #4	2015-05-19	48.390 mi
Registration #5	2016-05-18	54.259 mi
Registration #6	2017-05-04	61.801 mi
Registration #7	2018-05-02	68.608 mi
Registration #8	2019-05-13	74.781 mi
Registration #9	2019-05-13	74.781 mi
Registration #10	2020-11-16	76.507 mi
Registration #11	2020-11-16	76.507 mi
Registration #12	2020-11-16	76.507 mi
Registration #13	2020-11-16	76.507 mi
Registration #14	2020-11-16	76.507 mi
Registration #15	2020-11-16	76.507 mi
Registration #16	2020-11-16	76.507 mi
Registration #17	2020-11-16	76.507 mi
Registration #18	2020-11-16	76.507 mi
Registration #19	2020-11-16	76.507 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1493 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1684 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	882769