



RENAULT

SA64FTK


report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	White
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	81 kW / 110 HP / 110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	88.3 mpg
Consumption combined	80.7 mpg
CO2 emission	90 g/km
CO2 label	A







Internet history

Entry 2

Date	2023-12-12
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2021-08-03
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-26
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	20
Total items failed	9

MOT #10	2023-09-26 11:32
---------	------------------

MOT test number	692481578549
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-09-26
------------------	------------

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Service brake binding but not excessively Both sides rear (1.2.1 (f))
- Advice** Undertrays fitted
- Minor** Drive shaft joint constant velocity boot severely deteriorated Both sides front outer Strong advise O/S (6.1.7 (g) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened pads getting low (1.1.14 (a) (ii))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened pads appear ok (1.1.14 (a) (ii))
- Minor** Windscreen wiper blade defective Both sides front (3.4 (b) (i))

**MOT #9**

2022-09-27 14:38

**MOT test number**

227917097587

**Result**

✓ Passed

**Advice** Service brake binding but not excessively Both sides rear (1.2.1 (f))**Advice** Both sides front outer cv boots deteriorated**Minor** Windscreen wiper blade defective Both sides front (3.4 (b) (i))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Hand brake lever has little reserve travel**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #8**

2022-09-21 14:12

**MOT test number**

275952373575

**Result**

✗ Failed

**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Windscreen wiper blade defective Both sides front (3.4 (b) (i))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Hand brake lever has little reserve travel**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Service brake binding but not excessively Both sides rear (1.2.1 (f))**Advice** Both sides front outer cv boots deteriorated

**MOT #7** 2021-08-18 14:09**MOT test number** 796515767647**Result** ✓ Passed**MOT #6** 2020-07-28 11:17**MOT test number** 997972742000**Result** ✓ Passed**MOT #5** 2019-07-31 15:37**MOT test number** 639659118956**Result** ✓ Passed**MOT #4** 2019-07-31 11:54**MOT test number** 832508593562**Result** ✗ Failed

**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #3** 2018-07-23 14:02**MOT test number** 758249709779**Result** ✓ Passed**MOT #2** 2018-07-12 09:59**MOT test number** 676315784999**Result** ✗ Failed

**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Fail** Offside Front Position lamp not working (4.2.1 (a))

**Fail** Nearside Front Position lamp not working (4.2.1 (a))



MOT #1	2017-09-27 14:07
MOT test number	617583462323
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
26 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	26 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-03-29
Current registration	*****
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-30
Last registration	2023-09-26
Complete history	<a href="#">See info</a>



Registration #1	2014-09-30	15 mi
Registration #2	2017-09-27	28.737 mi
Registration #3	2018-07-12	32.263 mi
Registration #4	2018-07-23	32.323 mi
Registration #5	2019-07-31	38.633 mi
Registration #6	2019-07-31	38.640 mi
Registration #7	2019-09-26	38.640 mi
Registration #8	2019-09-26	38.640 mi
Registration #9	2019-09-26	38.640 mi
Registration #10	2019-09-26	38.640 mi
Registration #11	2019-09-26	38.640 mi
Registration #12	2019-09-26	38.640 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	83%
Children	78%
Pedestrian	60%
Safety systems	56%
Overall rating	72%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2037 mm
Height	1423 mm
Length	4312 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D510601