





report date: 2024-03-28

#### General information

Make	MINI
Model	MINI (R60) COOPER SD
Colour	White
Year of manufacture	2013
Top speed	134 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	141 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/13



## Internet history

#### Entry 1

Date 2022-01-18

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



# MOT history

MOT expiry date	2025-02-25
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	12
Total items failed	14

MOT #12	2024-02-26 17:30
MOT test number	760495992375
Result	✓ Passed
Next expiry date	2025-02-25

MOI #	11	2024-02-16 07:54
MOT to	est number	689220315008
Result		<b>×</b> Failed
Fail	Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Fail	Nearside Rear Tyre has a lump, caused by separation or partial failure of its struc	cture (5.2.3 (d) (ii))
Fail	Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail	Offside Rear Tyre has a lump, caused by separation or partial failure of its struct	ure (5.2.3 (d) (ii))

CarCheck.co.uk page 3/13



**MOT #10** 2023-06-16 10:40

MOT test number 810329968477

**Result** ✓ Passed

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2023-06-16 08:37

MOT test number 274258631400

Result X Failed

**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Front Windscreen washer not working (3.5 (a))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Central Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Offside Rear Rear fog lamp likely to become detached (4.5.1 (c) (ii))

**MOT #8** 2022-01-29 12:54

MOT test number 488224612733

Result 

Passed

CarCheck.co.uk page 4/13



MOT #7 2021-02-04 14:16

**MOT test number** 249270509642

Result \rightarrow Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Lower arm rear bush (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Lower arm rear bush (5.3.4 (a) (i))

MOT #6 2020-02-17 09:41

**MOT test number** 667281724106

MOT #5 2020-02-12 10:34

**MOT test number** 636217945429

**Result** X Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm splits on inner wall also (5.2.3 (e))

**MOT #4** 2019-02-09 09:40

MOT test number 234728527222

Result 

Passed

Advice Multi function warning lamp illuminated

(i))

**Advice** 

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b)

MOT #3 2019-02-09 09:40

**MOT test number** 792170403564

**Result** X Failed

**Pass with rectification** Headlamp aim too low both (4.1.2 (a))

Multi function warning lamp illuminated

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

CarCheck.co.uk page 5/13



MOT #2	2018-02-10 13:06
MOT test number	210505978511
Result	✓ Passed
MOT #1	2016-06-11 10:31
MOT test number	155080931008
Result	<b>✓</b> Passed

CarCheck.co.uk page 6/13



#### Tax & MOT check



Expires: 25 February 2025

**✓** MOT

Tax status

Days left

81 days too late

MOT expiry date

25 February 2025

Full MOT history

See MOT history

#### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
THE STATE OF THE S	
********	
***************************************	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	TK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-28
Last registration	2024-02-26
Complete history	See info



Registration #1	2013-03-28	17 mi
Registration #2	2016-06-11	44.512 mi
Registration #3	2018-02-10	65.190 mi
Registration #4	2019-02-09	77.445 mi
Registration #5	2019-02-09	77.445 mi
Registration #6	2020-02-12	90.040 mi
Registration #7	2020-02-17	90.040 mi
Registration #8		11.177 es
Registration #9		11.777 es
Registration #10		11.177 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 ms

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 12/13



## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1683 mm
Height	1384 mm
Length	3734 mm
Wheel base	2467 mm
Kerb weight	1175 kg
Max. allowed weight	1465 kg

# Additional information

Fuel tank capacity	40 I	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	2 page :	13/13

Number of axles 2

Engine number 72078312