



report date: 2024-03-29

General information

Make	AUDI
Model	A6 TDI DPF SE
Colour	Black
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	10.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.8 mpg
CO2 emission	178 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-05-23
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-12
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	27
Total items failed	8

MOT #17	2024-04-12 11:47
MOT test number	247410092308
Result	✓ Passed
Next expiry date	2025-04-12
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2023-04-12 09:03
MOT test number	629677928736
Result	✓ Passed

MOT #15	2022-04-13 14:42
MOT test number	964897750935
Result	✓ Passed
Advice	Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Exhaust has a minor leak of exhaust gases pipe (6.1.2 (a))



MOT #14

2022-04-06 17:08

MOT test number

244338735209

Result

✗ Failed

DANGEROUS Offside Front Tyre has a tear, caused by separation or partial failure of its structure and low tread (5.2.3 (d) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Exhaust has a minor leak of exhaust gases pipe (6.1.2 (a))

Advice Rear heat shield insecure

Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear tyres out of shape

MOT #13

2021-05-22 13:20

MOT test number

109827432561

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge centre (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge centre (5.2.3 (e))

MOT #12

2019-07-30 10:55

MOT test number

179881235699

Result

✓ Passed

**MOT #11** 2019-07-24 16:12**MOT test number** 167581161578**Result** ✗ Failed**MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**MAJOR** Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))**MOT #10** 2018-07-10 15:28**MOT test number** 481352000319**Result** ✓ Passed**MOT #9** 2017-07-06 15:07**MOT test number** 260210739466**Result** ✓ Passed**MOT #8** 2016-07-05 14:52**MOT test number** 695112046273**Result** ✓ Passed**MOT #7** 2015-07-08 09:47**MOT test number** 979219485158**Result** ✓ Passed**MOT #6** 2014-07-12 13:16**MOT test number** 955253994177**Result** ✓ Passed**Notice** Engine management lamp on



MOT #5	2013-07-18 15:55
MOT test number	555319093118
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4	2013-07-15 13:53
MOT test number	285746893420
Result	✗ Failed
Fail	Hazard warning switch faulty (1.4.B.1d)
Fail	Offside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
Notice	Air filter box not fitted properly
Fail	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Fail	Nearside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
Fail	Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Registration plate lamp not working (1.1.C.1d)

MOT #3	2012-06-22 16:01
MOT test number	596334972150
Result	✓ Passed

MOT #2	2011-07-13 09:52
MOT test number	807854691163
Result	✓ Passed
Notice	Engine management lamp on



MOT #1	2010-05-03 14:53
MOT test number	751693220104
Result	✓ Passed
<div>Notice Offside rear tyre wearing on outer edge</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
12 April 2025

Tax status	Valid until 1 December
Days left	216
MOT expiry date	12 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	YD07SUA
Plate since	2019-09-29
Current registration	YD07SUA
Plate since	2019-09-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-16
Last registration	2024-04-12
Complete history	See info



Registration #1	2007-03-16	26 mi
Registration #2	2010-05-03	85.173 mi
Registration #3	2011-07-13	98.188 mi
Registration #4	2012-06-22	112.166 mi
Registration #5	2013-07-15	125.261 mi
Registration #6	2013-07-18	125.291 mi
Registration #7	2014-07-12	133.215 mi
Registration #8	2015-07-08	141.688 mi
Registration #9	2016-07-05	146.840 mi
Registration #10	2017-07-06	149.120 mi
Registration #11	2018-07-06	151.400 mi
Registration #12	2019-07-06	153.680 mi
Registration #13	2020-07-06	155.960 mi
Registration #14	2021-07-06	158.240 mi
Registration #15	2022-07-06	160.520 mi
Registration #16	2023-07-06	162.800 mi
Registration #17	2024-07-06	165.080 mi
Registration #18	2025-07-06	167.360 mi
Registration #19	2026-07-06	169.640 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1855 mm
Height	1463 mm
Length	4933 mm
Wheel base	2843 mm
Kerb weight	1635 kg
Max. allowed weight	2265 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	BRE 142367