





General information

Make	PEUGEOT
Model	5008 BLUEHDI S/S GT LINE
Colour	Black
Year of manufacture	2017
Top speed	115 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	120 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	72.4 mpg
Consumption combined	67.3 mpg
CO2 emission	114 g/km
CO2 label	С







Internet history

Date Pictures 2021-06-30

32

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-23
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	11
Total items failed	6

MOT #15	2023-11-24 15:45
MOT test number	552103167914
Result	✓ Passed
Next expiry date	2024-11-23

MOT #14	2023-05-05 12:59
MOT test number	294025015189
Result	✓ Passed
Minor Nearside Rear Registration plate lamp inoperative in the case of multipl (4.7.1 (b) (i))	e lamps or light sources
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))	
Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))	
Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	

MOT #13	2022-11-07 11:51
MOT test number	958620799676
Result	✓ Passed
MOT #12	2022-05-05 15:11
MOT test number	313265751320

MOT test number	313265751320
Result	✓ Passed





MOT #11	2022-05-05 15:11
MOT test number	545354134802
Result	× Failed
Pass with rectification dirt (5.3.4 (b) (ii))	Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #10	0 2021-1:	1-05 14:50
MOT test	t number 4406	33044114
Result		✓ Passed
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Minor (4.7.1 (b)	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light so (i))	urces

MOT #9	2021-05-08 10:47
MOT test number	444776969169
Result	✓ Passed
AdviceFront Brake disc worn, pitted or scored, but not seriously weakened (1.1.1AdviceRear Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	

MOT #8	2020-08-28 14:28
MOT test number	729986098116
Result	✓ Passed





MOT #7	2020-08-28 14:28
MOT test number	309516568083
Result	× Failed
Pass with rectification	Nearside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
Pass with rectification	Stop lamp(s) not working both rear (4.3.1 (a) (ii))

MOT #6	2020-03-02 11:19
MOT test number	293385770451
Result	✓ Passed

MOT #5	2020-03-02 11:19
MOT test number	327305287669
Result	× Failed
Pass with rectification lamps both rear (4.7.2 (a))	Registration plate lamp does not illuminate simultaneously with the position
Pass with rectification	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

МОТ #4	2019-08-05 14:18
MOT test number	519143201956
Result	✓ Passed

MOT #3	2019-	02-05 13:38
MOT test	t number 32 [°]	7007104187
Result		🗸 Passed
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	

MOT #2	2018-08-06 15:00
MOT test number	735648648959
Result	✓ Passed





MOT #1	2018-02-07 14:39
MOT test number	515340378424
Result	✓ Passed



Tax & MOT check

Taxed Tax due: 1 November 2024	MOT Expires: 23 November 2024
Tax status	Valid until 1 November
Days left	185
MOT expiry date	23 November 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE D
Category	 L CENPE
Туре	K K
Damage 2	AMPL
Date	
Category	 AMPL
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	

More info >





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2017-01-31
Last registration	2023-11-24
Complete history	See info



Registration #2 2018-02-07 14.381 mi Registration #3 2018-02-07 14.381 mi Registration #3 2018-02-05 22.919 mi Registration #4 2019-02-05 35.974 mi Registration #5 2019-02-05 39.325 mi Registration #6 2020-03-02 43.091 mi Registration #7 2020-03-02 43.091 mi Registration #8 2020-08-28 57.160 mi Registration #9 2020-08-28 57.160 mi Registration #10 T T Registration #11 T T Registration #12 T T Registration #13 T T Registration #14 T T Registration #15 T T Registration #16 T T			
Registration #3 2018-08-06 22.919 mi Registration #4 2019-02-05 35.974 mi Registration #5 2019-08-05 39.325 mi Registration #6 2020-03-02 43.091 mi Registration #7 2020-03-02 43.091 mi Registration #7 2020-08-28 57.160 mi Registration #9 2020-08-28 57.160 mi Registration #10 T T Registration #11 T T Registration #12 T T Registration #13 T T Registration #14 T T T Registration #15 T T T Registration #16 T T T	Registration #1	2017-01-31	11 mi
Registration #4 2019-02-05 35.974 mi Registration #5 2019-08-05 39.325 mi Registration #6 2020-03-02 43.091 mi Registration #7 2020-03-02 43.091 mi Registration #7 2020-08-28 57.160 mi Registration #9 2020-08-28 57.160 mi Registration #10 T T Registration #11 T T Registration #12 T T Registration #13 T T Registration #14 T T Registration #15 T T	Registration #2	2018-02-07	14.381 mi
Registration #5 2019-08-05 39.325 mi Registration #6 2020-03-02 43.091 mi Registration #7 2020-03-02 43.091 mi Registration #8 2020-08-28 57.160 mi Registration #9 2020-08-28 57.160 mi Registration #10 T T Registration #11 T T Registration #12 T T Registration #13 T T Registration #14 T T Registration #15 T T	Registration #3	2018-08-06	22.919 mi
Registration #6 2020-03-02 43.091 mi Registration #7 2020-03-02 43.091 mi Registration #8 2020-08-28 57.160 mi Registration #9 2020-08-28 57.160 mi Registration #10 57.160 mi Registration #11 57.160 mi Registration #12 57.160 mi Registration #13 57.160 mi Registration #14 57.160 mi Registration #14 57.160 mi Registration #15 57.160 mi	Registration #4	2019-02-05	35.974 mi
Registration #7 2020-03-02 43.091 mi Registration #8 2020-08-28 57.160 mi Registration #9 2020-08-28 57.160 mi Registration #10 Registration #11 Registration #12 Registration #13 Registration #14 Registration #15	Registration #5	2019-08-05	39.325 mi
Registration #82020-08-2857.160 miRegistration #92020-08-2857.160 miRegistration #10Registration #11Registration #12Registration #13Registration #14Registration #15Registration #16	Registration #6	2020-03-02	43.091 mi
Registration #92020-08-2857.160 miRegistration #10Control of the second se	Registration #7	2020-03-02	43.091 mi
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	Registration #8	2020-08-28	57.160 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	Registration #9	2020-08-28	57.160 mi
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	Registration #10		11.777 esi
Registration #13 Registration #14 Registration #15 Registration #16	Registration #11		11.777 mi
Registration #14 Registration #15 Registration #16	Registration #12		11.777 esi
Registration #15 Registration #16	Registration #13		11.777 mi
Registration #16	Registration #14		11.777 esi
	Registration #15		11.777 mi
Peristration #17	Registration #16		11.777 est
	Registration #17		11.117 esi
	Registration #1/		





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	86%
Children	81%
Pedestrian	31%
Safety systems	97%
Overall rating	75%
Video	see crash video



Dimensions & weight	
Width	1841 mm
Height	1624 mm
Length	4447 mm
Wheel base	2675 mm
Kerb weight	1315 kg
Max. allowed weight	1990 kg
Additional information	
Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	JBHY3062763