



RENAULT

LY08GNP

report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE SCENIC DYNAMIQUE S VVT 111 SCENIC
Colour	Gold
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	150 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.2 mpg







Internet history

Entry 1

Date	2022-06-12
Pictures	13
Listing price	View report



source: cargurus.co.uk



MOT history

MOT #19

2023-08-30 10:52

MOT test number

958726358607

Result

✗ Failed

MAJOR Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Steering system slightly rough nearside and offside front top mountings (2.1.1 (a))**MAJOR** Electronic parking brake warning indicates a malfunction (1.1.6 (e))**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Electronic parking brake control defective so that it cannot be satisfactorily operated (1.1.6 (d))

MOT #18

2022-07-29 15:30

MOT test number

584307124002

Result

✓ Passed

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Rear Shock absorbers has slight external damage to the casing both rear slightly corroded (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17

2021-10-01 11:34

MOT test number

188024850994

Result

✓ Passed

**MOT #16**

2021-10-01 08:38

MOT test number

637305909000

Result**✗ Failed**

- Advice** Offside Front Brake disc has grease on it
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front road spring rubbing on spring cup
- Advice** Offside Front top suspension mounting bearing worn
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Offside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #15

2020-09-28 16:16

MOT test number

738372492218

Result**✓ Passed****MOT #14**

2019-10-04 12:06

MOT test number

553765379136

Result**✓ Passed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Steering linkage ball joint has slight play (2.1.3 (b) (i))

MOT #13

2019-10-02 10:29

MOT test number

643630412791

Result**✗ Failed**

- MAJOR** Nearside Front Steering rack has excessive free play detected at the steering wheel (steering rack fitted) Steering rack-end badly worn (2.3 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #12**

2018-05-03 14:41

MOT test number

683476109923

Result

✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Play in steering rack inner joint(s)**Advice** Offside front tyre wearing on edges of tread**MOT #11**

2018-05-03 08:47

MOT test number

117796180949

Result

✗ Failed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Play in steering rack inner joint(s)**Advice** Offside front tyre wearing on edges of tread**Advice** Offside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)**Fail** Offside Steering rack gaiter insecure (2.2.D.2d)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #10**

2017-05-02 08:00

MOT test number

353007135904

Result

✓ Passed

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside front tyre wearing on outer edge of tread**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Play in steering rack inner joint(s)**Advice** Offside rear tyre wearing on outer edge of tread & perished on tread



MOT #9 2017-05-02 08:00

MOT test number 968676353755

Result ✗ Failed

Advice Play in steering rack inner joint(s)

Advice Nearside front tyre wearing on outer edge of tread

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice Offside rear tyre wearing on outer edge of tread & perished on tread

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #8 2016-04-15 15:17

MOT test number 499784312739

Result ✓ Passed

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice Front tyres wearing on edges of tread

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Play in steering rack inner joints

**MOT #7** 2016-04-15 07:55**MOT test number** 852911983949**Result** ✗ Failed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Front tyres wearing on edges of tread**Fail** Nearside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Play in steering rack inner joints**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #6** 2015-04-29 08:47**MOT test number** 357309715194**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #5** 2014-05-02 14:00**MOT test number** 538782324147**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2014-05-01 08:43**MOT test number** 745811824109**Result** ✗ Failed**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Stop lamp has less than 50% of the light sources illuminating (1.2.1b)**Notice** Nail in offside front tyre**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Upper Stop lamp not working (1.2.1b)**Fail** Offside Stop lamp has less than 50% of the light sources illuminating (1.2.1b)**Notice** Offside rear tyre badley perished**MOT #3** 2013-05-08 12:18**MOT test number** 537948923145**Result** ✓ Passed**MOT #2** 2012-09-25 11:28**MOT test number** 376639162225**Result** ✓ Passed**MOT #1** 2011-05-31 11:01**MOT test number** 228351651100**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	LY08GNP
Plate since	2019-03-29
Current registration	LY08GNP
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-06-24
Last registration	2023-08-30
Complete history	See info



Registration #1	2008-06-24	28 mi
Registration #2	2011-05-31	10.147 mi
Registration #3	2012-09-25	14.882 mi
Registration #4	2013-05-08	16.608 mi
Registration #5	2014-05-01	31.275 mi
Registration #6	2014-05-02	31.290 mi
Registration #7	2015-04-29	45.960 mi
Registration #8	2016-04-15	61.111 mi
Registration #9	2016-04-15	61.128 mi
Registration #10	2017-05-02	77.201 mi
Registration #11	2017-05-02	77.201 mi
Registration #12	2018-05-02	93.275 mi
Registration #13	2019-05-02	109.349 mi
Registration #14	2020-05-02	125.423 mi
Registration #15	2021-05-02	141.497 mi
Registration #16	2022-05-02	157.571 mi
Registration #17	2023-05-02	173.645 mi
Registration #18	2024-05-02	189.719 mi
Registration #19	2025-05-02	205.793 mi
Registration #20	2026-05-02	221.867 mi
Registration #21	2027-05-02	237.941 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1701 mm
Length	4259 mm
Wheel base	2685 mm
Kerb weight	1320 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

D053480