





General information

| Make | BMW |
|---------------------|----------------------|
| Model | X4 XDRIVE20D M SPORT |
| Colour | Black |
| Year of manufacture | 2015 |
| Top speed | 132 mph |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 188 BHP |
|-------------------------|---------------------|
| Max. torque | 400 Nm at 1.750 rpm |
| Engine capacity | 1.995 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 49.6 mpg |
| Consumption extra urban | 56.5 mpg |
| Consumption combined | 54.3 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |





Internet history

| Entry 1 | |
|---------------|-------------|
| Date | 2021-10-03 |
| Pictures | 12 |
| Listing price | View report |
| | |



source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-04-17 |
|--------------------|------------|
| MOT pass rate | 86 % |
| MOT passed | 6 |
| Failed MOT tests | 1 |
| Total advice items | 12 |
| Total items failed | 1 |

| MOT #7 | 2024-04-17 11:48 |
|--|------------------|
| MOT test number | 293746356353 |
| Result | 🗙 Failed |
| Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i)) | |
| Advice Offside Play in steering rack inner joint(s) | |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | |

| MOT #6 | | 2023-04-18 16:29 |
|--|--|------------------|
| MOT test | number | 309317698125 |
| Result | | ✓ Passed |
| Advice | Offside Front Play in steering rack inner joint(s) | |
| Minor Nearside Rear Stop lamp(s) lens defective which has no effect on emitted light (4.3.1 (b) (i)) | | |
| | | |

| MOT #5 | 2022-10-08 12:47 |
|-----------------|------------------|
| MOT test number | 991130075926 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2021-09-30 07:44 |

| MOT test number | 886390196299 |
|-----------------|--------------|
| Result | ✓ Passed |





| MOT #3 | | 2020-11-24 11:23 |
|----------|--|------------------|
| MOT test | number | 642026387224 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| мот | #2 | |
|-----|------|--------|
| мот | test | number |

Result

2019-10-29 09:24 840808724869

| | 🗸 Passed |
|--|----------|
| | |

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

| MOT #1 | 2018-10-01 08:28 |
|-----------------------------------|------------------|
| MOT test number | 901655535041 |
| Result | ✓ Passed |
| Advice Under Trays Fitted | |
| Advice Nearside Rear Nail in tyre | |



Tax & MOT check

| √ Taxed | Х MOT |
|--------------------------|---------------------------|
| Tax due: 1 April 2025 | Expired: 17 April 2024 |
| Tax status | Valid until 1 April |
| Days left | 338 |
| MOT expiry date | 17 April 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |





Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | |
| Category | Lampe |
| Туре | |
| Damage 2 | AMPLE |
| Damage 2 | E E E E |
| Date | S. |
| Category | ame |
| Туре | |

Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| *********** | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this BMW had different number plates. | |
| Number of plates | 7 |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | |





Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2015-06-30 |
| Last registration | 2024-04-17 |
| Complete history | See info |



| Registration #1 | 2015-06-30 | 7 mi |
|-----------------|------------|------------|
| Registration #2 | 2018-10-01 | 20.136 mi |
| Registration #3 | 2019-10-29 | 24.331 mi |
| Registration #4 | 2020-11-24 | 27.115 mi |
| Registration #5 | 2021-09-30 | 29.125 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 esi |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| S0482 | |
| \$0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 88% |
| Children | 83% |
| Pedestrian | 53% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1881 mm |
| Height | 1624 mm |
| Length | 4671 mm |
| Wheel base | 2810 mm |
| Kerb weight | 1745 kg |
| Max. allowed weight | 2335 kg |
| Additional information | |
| Fuel tank capacity | 67 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|----------|
| Engine number | 53579218 |