





General information

Make	MERCEDES
Model	CLK CLK350 SPORT
Colour	Silver
Year of manufacture	2005
Top speed	155 mph
0 - 60 mph	6.7 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	268 BHP
Max. torque	350 Nm at 3.000 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.3 mpg
Consumption extra urban	36.7 mpg
Consumption combined	27.7 mpg
CO2 emission	244 g/km
CO2 label	L







Internet history		
Entry 1		
Date	2021-11-13	
Pictures	0	
Listing price	View report	

source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-20
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	24
Total items failed	5

MOT #19	2023-12-21 11:11
MOT test number	519417124608
Result	✓ Passed
Next expiry date	2024-12-20
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #18	2022-07-22 10:05
MOT test number	934677376464
Result	✓ Passed
Advice Rear Coil spring corroded both rears (5.3.1 (b) (i))	
Advice Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	

MOT #17	2021-07-12 09:03
MOT test number	873988962468
Result	✓ Passed
Result	✓ Passe

MOT #16	2021-07-02 11:07
MOT test number	554764921520
Result	🗙 Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	





MOT #15	2020-08-10 15:39
MOT test number	693058675337
Result	✓ Passed
MOT #14	2019-07-10 11:23
MOT test number	821499214617
Result	✓ Passed

MOT #13	2018-08-06 13:22
MOT test number	622986215944
Result	✓ Passed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #12	2017-07-20 15:21
MOT test number	644768023022
Result	✓ Passed
Advice EXHAUST HANGER CORRODED	
Advice Nearside Front TYRE WORN ON OUTER EDGE	

MOT #11	2016-07-11 15:04
MOT test number	851685741229
Result	✓ Passed



M500NJD
report date: 2024-03-29

MOT #10		2015-07-23 16:20
MOT test	number	799554905272
Result		✓ Passed
Notice	O/s/f tyre bald outer edge	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	N/s/r tyre has split on inner sidewall not down to ply/cords	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
MOT #9		2015-07-23 15:03
MOT test	number	948394405257
_		

Result	× Failed	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	O/s/f tyre bald outer edge	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	N/s/r tyre has split on inner sidewall not down to ply/cords	
	ffside Front Lower Suspension arm ball joint dust cover excessively damaged so that it no longer the ingress of dirt (2.4.G.2)	

MOT #8		2014-07-02 16:53
MOT test	number	128683684178
Result		✓ Passed
Notice	Slight flat spot to nearside rear alloy wheel	
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Notice	Offside front tyre worn low on edges	



M500NJD
report date: 2024-03-29

MOT #7		2014-07-02 16:53
MOT test number		207563984147
Result		🗙 Failed
Advice Parking brake le	ver has little reserve travel (3.1.6b)	
Notice Slight flat spot to	o nearside rear alloy wheel	
Pass with rectification	Nearside Front Headlamp aim too high (1.8)	
Pass with rectification	Nearside Front Tyre has a cut in excess of the requiren	nents deep enough to
reach the ply or cords (4.1.	D.1a)	
Notice Offside front tyre worn low on edges		
Pass with rectification	Offside Front Headlamp aim too high (1.8)	

MOT #6	2013-07-18 12:45
MOT test number	449659793143
Result	✓ Passed

MOT #5	2012-07-23 16:43
MOT test number	576285302231
Result	✓ Passed

MOT #4		2011-07-27 12:26
MOT test r	number	925648801252
Result		✓ Passed
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)	

MOT #3	2010-07-08 13:26
MOT test number	620599880122
Result	✓ Passed





MOT #2	2009-07-20 14:49
MOT test number	504541309227
Result	✓ Passed
MOT #1	2008-07-22 17:18
MOT test number	712974608277
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 August 2024	✓ MOT Expires: 20 December 2024
Tax status	Valid until 1 August
Days left	94
MOT expiry date	20 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	VAMPLE
Date	
Category	AMP
Туре	

Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
See in this check in this MERCEDES had uncreate number plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Current registration	
Current registration Plate since	





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-07-29
Last registration	2023-12-21
Complete history	<u>See info</u>



Registration #1	2005-07-29	22 mi
Registration #2	2008-07-22	14.655 mi
Registration #3	2009-07-20	17.935 mi
Registration #4	2010-07-08	19.922 mi
Registration #5	2011-07-27	23.734 mi
Registration #6	2012-07-23	28.059 mi
Registration #7	2013-07-18	31.996 mi
Registration #8	2014-07-02	36.237 mi
Registration #9	2015-07-23	41.259 mi
Registration #10	2015-07-23	41.259 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 mi
Registration #19		11.777 mi
Registration #20		
Registration #20		





Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1735 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	62
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27296030124430