



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	107 ACCESS
Colour	Red
Year of manufacture	2012
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A







Internet history

Entry 1

Date	2021-09-09
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-27
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	52
Total items failed	8

MOT #13	2023-09-29 14:16
MOT test number	603586699219
Result	✓ Passed
Next expiry date	2024-10-27
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Tyre worn close to legal limit/worn on edge both also cracked and perished (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Brake pipe corroded, covered in grease or other material both pipes to flexi hose (1.1.11 (c))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2023-09-29 09:45

**MOT test number**

700482092763

**Result**

✗ Failed

**Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Fail**

Nearside Rear Tyre not fitted in accordance with side wall instructions also cracked /perished (5.2.3 (i))

**Advice**

Front Tyre worn close to legal limit/worn on edge both also cracked and perished (5.2.3 (e))

**Advice**

Rear Brake pipe corroded, covered in grease or other material both pipes to flexi hose (1.1.11 (c))

**Advice**

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice**

Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

**Minor**

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #11**

2022-10-18 09:53

**MOT test number**

540957822518

**Result**

✓ Passed

**MOT #10**

2021-10-28 11:36

**MOT test number**

262062496546

**Result**

✓ Passed

**MOT #9**

2021-10-28 07:31

**MOT test number**

160132721883

**Result**

✗ Failed

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**MOT #8**

2020-12-23 09:31

**MOT test number**

948502830216

**Result**

✓ Passed

- Advice** Nearside Brake pipe corroded, covered in grease or other material Main (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Brake pipe corroded, covered in grease or other material Main (1.1.11 (c))

**MOT #7**

2019-06-19 13:04

**MOT test number**

633250496778

**Result**

✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material main (1.1.11 (c))

**MOT #6** 2019-06-19 08:26**MOT test number** 397370772618**Result** ✗ Failed

- Advice** Spare tyre defective flat
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material main (1.1.11 (c))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #5** 2018-06-30 11:52**MOT test number** 606443251953**Result** ✓ Passed

- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement Drop link bush perished (5.3.4 (a) (i))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement Drop link bush perished (5.3.4 (a) (i))

**MOT #4** 2017-07-10 10:26**MOT test number** 709011326122**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit Inner and outer edge (4.1.E.1)
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre worn close to the legal limit Inner and outer edge (4.1.E.1)
- Advice** Nearside Front Nail in tyre

**MOT #3** 2017-07-07 13:57**MOT test number** 658321387821**Result** ✗ Failed

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre cracked and perished
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)
- Advice** Nearside Rear Tyre cracked and perished

**MOT #2** 2016-07-08 13:13**MOT test number** 820331491977**Result** ✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Offside Rear tyre cracking
- Advice** Nearside Rear tyre cracking

**MOT #1** 2015-07-11 10:07**MOT test number** 179182695169**Result** ✓ Passed

- Notice** Frront brake pads appear low
- Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
27 October 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	27 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	 <b>ND12UHV</b>
Plate since	2019-03-29
Current registration	 <b>ND12UHV</b>
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-06-30
Last registration	2023-09-29
Complete history	<a href="#">See info</a>



Registration #1	2012-06-30	20 mi
Registration #2	2015-07-11	27.450 mi
Registration #3	2016-07-08	37.986 mi
Registration #4	2017-07-07	45.989 mi
Registration #5	2017-07-10	46.031 mi
Registration #6	2018-06-30	49.974 mi
Registration #7	2019-06-19	58.277 mi
Registration #8	2019-06-19	58.278 mi
Registration #9	2019-06-19	58.277 mi
Registration #10	2019-06-19	58.277 mi
Registration #11	2019-06-19	58.277 mi
Registration #12	2019-06-19	58.277 mi
Registration #13	2019-06-19	58.277 mi
Registration #14	2019-06-19	58.277 mi
Registration #15	2019-06-19	58.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	7155098