



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA VTX 16V PICASSO
Colour	Silver
Year of manufacture	2007
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 2


Date	2023-02-24
Pictures	16
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-09-06
Pictures	13
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-08-31
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	12
Total items failed	3

## MOT #17 2023-08-23 11:20

MOT test number 915393285151

Result ✓ Passed

Next expiry date 2024-08-31

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Steering rack has slight fluid leaking**Advice** Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

## MOT #16 2022-09-01 10:38

MOT test number 692423628082

Result ✓ Passed

## MOT #15 2021-08-31 15:09

MOT test number 489642713349

Result ✓ Passed

**MOT #14** 2021-08-26 16:34**MOT test number** 993143221301**Result** ✗ Failed**Fail** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Inner Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #13** 2020-08-11 13:36**MOT test number** 517122585642**Result** ✓ Passed**MOT #12** 2019-06-10 13:46**MOT test number** 165729453868**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear of wishbone (5.3.4 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear of wishbone (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #11** 2018-06-05 12:51**MOT test number** 700324210247**Result** ✓ Passed**MOT #10** 2017-05-25 09:18**MOT test number** 890308872500**Result** ✓ Passed



<b>MOT #9</b>	2016-05-26 12:03
---------------	------------------

<b>MOT test number</b>	868471397344
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #8</b>	2015-05-27 11:39
---------------	------------------

<b>MOT test number</b>	936067945197
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #7</b>	2014-05-28 11:53
---------------	------------------

<b>MOT test number</b>	335558444175
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #6</b>	2013-06-03 09:56
---------------	------------------

<b>MOT test number</b>	895214353163
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2012-05-21 17:06
---------------	------------------

<b>MOT test number</b>	206502942499
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2011-05-18 16:58
---------------	------------------

<b>MOT test number</b>	367098031179
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Notice</b>	Nail in offside rear tyre
---------------	---------------------------

<b>MOT #3</b>	2010-06-09 16:52
---------------	------------------

<b>MOT test number</b>	800210760181
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



MOT #2	2010-01-26 11:48
MOT test number	530876620034
Result	✓ Passed

MOT #1	2010-01-26 11:48
MOT test number	122736220465
Result	✗ Failed

Pass with rectification

 Front Windscreen washer provides insufficient washer liquid (8.2.3)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
31 August 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	31 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 <b>VK07YXO</b>
Plate since	2019-09-29
Current registration	 <b>VK07YXO</b>
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-21
Last registration	2023-08-23
Complete history	<a href="#">See info</a>



Registration #1	2007-03-21	19 mi
Registration #2	2010-01-26	14.743 mi
Registration #3	2010-06-09	15.898 mi
Registration #4	2011-05-18	19.960 mi
Registration #5	2012-05-21	23.341 mi
Registration #6	2013-06-03	27.400 mi
Registration #7	2014-05-28	31.643 mi
Registration #8	2015-05-27	35.769 mi
Registration #9	2016-05-26	39.845 mi
Registration #10	2017-05-25	45.771 mi
Registration #11	2018-05-24	51.697 mi
Registration #12	2019-05-23	57.623 mi
Registration #13	2020-05-22	63.549 mi
Registration #14	2021-05-21	69.475 mi
Registration #15	2022-05-20	75.401 mi
Registration #16	2023-05-19	81.327 mi
Registration #17	2024-05-18	87.253 mi
Registration #18	2025-05-17	93.179 mi
Registration #19	2026-05-16	99.105 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6P3147628