



report date: 2024-03-29

General information

Make	FORD
Model	FIESTA BASE TDCI
Colour	White
Year of manufacture	2010
Top speed	100 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2025-03-24
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	20
Total items failed	33

MOT #19	2024-03-25 13:15
MOT test number	883223494708
Result	✓ Passed
Next expiry date	2025-03-24

**MOT #18**

2024-03-22 09:51

**MOT test number**

713343258167

**Result****✗ Failed**

- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))
- Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))
- Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))

**MOT #17**

2023-03-01 09:57

**MOT test number**

475048271156

**Result****✓ Passed****MOT #16**

2023-03-01 09:57

**MOT test number**

104663252517

**Result****✗ Failed**

- Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #15** 2022-02-09 11:36**MOT test number** 509850796302**Result** ✓ Passed

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

**MOT #14** 2022-02-09 11:36**MOT test number** 490840093531**Result** ✗ Failed

**Pass with rectification** Offside Stop lamp(s) not working Replaced bulb (4.3.1 (a) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Pass with rectification** Offside Headlamps matched pair are not the same colour Dipp bulb blue, replaced bulb (4.1.4 (d))

**MOT #13** 2021-02-03 15:21**MOT test number** 943612600043**Result** ✓ Passed

**Advice** Brake pedal wearing smooth (1.1.2 (c))

**Advice** Steering rack noisy in operation

**MOT #12**

2021-02-02 15:09

**MOT test number**

968319073181

**Result****✗ Failed**

- Fail** Front Service brake excessively fluctuating (1.2.1 (e))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Offside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Steering rack noisy in operation
- Fail** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i))
- Advice** Rear Coil spring corroded o/s and n/s (5.3.1 (b) (i))

**MOT #11**

2020-02-18 12:23

**MOT test number**

767013707822

**Result****✓ Passed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2020-02-18 11:21

**MOT test number**

573829357117

**Result****✗ Failed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Rear Direction indicator incorrect colour both sides (4.4.3 (a))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Emissions not tested due to black smoke filling workshop (8.2.2.2 (e))**MOT #9**

2019-02-04 13:48

**MOT test number**

703836742819

**Result****✓ Passed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #8**

2019-02-04 09:20

**MOT test number**

184310209860

**Result****✗ Failed****Fail** Windscreen washer not working (3.5 (a))**Fail** Offside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Fail** Offside Headlamp not working on main beam (4.1.1 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2018-02-10 09:27**MOT test number** 939657072086**Result** ✓ Passed**MOT #6** 2017-02-15 11:50**MOT test number** 304766120063**Result** ✓ Passed**MOT #5** 2017-02-15 11:04**MOT test number** 797675443749**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2016-02-19 15:22**MOT test number** 112089640757**Result** ✓ Passed**Advice** Centre Rear back box corroded but not insecure**MOT #3** 2015-06-02 14:09**MOT test number** 436163455148**Result** ✓ Passed**Notice** Screw in nearside rear tyre**MOT #2** 2014-06-03 14:22**MOT test number** 227384254481**Result** ✓ Passed**Notice** Rear exhaust box corroded



MOT #1	2013-06-04 14:16
MOT test number	198525853109
Result	✓ Passed
<div>Notice Front inner brake pads worn thin</div>	





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
24 March 2025

<b>Tax status</b>	Valid until 1 October
-------------------	-----------------------

<b>Days left</b>	154
------------------	-----

<b>MOT expiry date</b>	24 March 2025
------------------------	---------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-06-23
Last registration	2024-03-25
Complete history	<a href="#">See info</a>



Registration #1	2010-06-23	20 mi
Registration #2	2013-06-04	26.664 mi
Registration #3	2014-06-03	36.599 mi
Registration #4	2015-06-02	46.428 mi
Registration #5	2016-02-19	51.267 mi
Registration #6	2017-02-15	64.046 mi
Registration #7	2017-02-15	64.046 mi
Registration #8	2018-02-10	77.535 mi
Registration #9	2019-02-04	97.763 mi
Registration #10	2019-02-04	97.763 mi
Registration #11	2019-02-04	97.763 mi
Registration #12	2019-02-04	97.763 mi
Registration #13	2019-02-04	97.763 mi
Registration #14	2019-02-04	97.763 mi
Registration #15	2019-02-04	97.763 mi
Registration #16	2019-02-04	97.763 mi
Registration #17	2019-02-04	97.763 mi
Registration #18	2019-02-04	97.763 mi
Registration #19	2019-02-04	97.763 mi
Registration #20	2019-02-04	97.763 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	AM25060