



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	CELICA VVTI
Colour	Black
Year of manufacture	2006
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-07-14
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-27
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	50
Total items failed	5

MOT #21	2024-02-21 13:22
MOT test number	940694709657
Result	✓ Passed
Next expiry date	2025-02-27
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20	2024-02-21 13:22
MOT test number	552328670350
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #19	2023-02-28 13:53
MOT test number	376675413088
Result	✓ Passed

MOT #18	2022-02-02 16:32
MOT test number	562824594632
Result	✓ Passed

**MOT #17**

2022-02-01 11:54

MOT test number

859951098697

Result**✗ Failed****MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge at limit (5.2.3 (e))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**DANGEROUS** Nearside Front Inner Tyre has a tear, caused by separation or partial failure of its structure wall (5.2.3 (d) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #16**

2021-01-30 08:29

MOT test number

537101670925

Result**✓ Passed****Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #15**

2020-02-01 09:12

MOT test number

794713300709

Result**✓ Passed****Minor** Offside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #14**

2019-02-02 11:11

MOT test number

455097041481

Result**✓ Passed****Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #13**

2018-02-02 12:52

MOT test number

296864523430

Result

✓ Passed

- Advice** Plastic sill covers fitted
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Plastic under-tray obscuring some testable components
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Road wheel slightly damaged outer rim (4.2.A.1a)

MOT #12

2017-02-02 12:53

MOT test number

638040506514

Result

✓ Passed

- Advice** Offside Rear brake disc modified but not seriously weakened (3.5.1n)
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Under engine tray obscuring some testable components
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Advise inspection and adjustment of rear brakes

MOT #11

2016-02-01 10:51

MOT test number

128884775680

Result

✓ Passed

- Advice** Under body shields obscuring some components
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Wheel rim has slight damage



MOT #10 2016-01-28 12:03

MOT test number 817178411312

Result ✗ Failed

- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Under body shields obscuring some components
- Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Wheel rim has slight damage
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #9 2015-01-22 10:32

MOT test number 348242525089

Result ✓ Passed

- Advice** Nearside Inner Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Outer Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #8

2015-01-22 10:32

MOT test number

236592925010

Result

✗ Failed

Pass with rectification Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Outer Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Inner Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7

2014-01-16 14:23

MOT test number

497736014090

Result

✓ Passed

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Nail in nearside rear tyre**Advice** Nearside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Under-trays fitted obscuring some underside components

MOT #6

2013-01-25 10:19

MOT test number

247765323047

Result

✓ Passed

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2013-01-25 10:19**MOT test number** 205885323017**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #4** 2012-01-26 13:13**MOT test number** 929166422089**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)**MOT #3** 2011-01-21 16:46**MOT test number** 845551121008**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2010-01-25 10:17**MOT test number** 142895820072**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2009-01-29 11:32**MOT test number** 163429429059**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
27 February 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	27 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	EN55SNU
Plate since	2024-03-28
Current registration	EN55SNU
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-02-02
Last registration	2024-02-21
Complete history	See info



Registration #1	2006-02-02	23 mi
Registration #2	2009-01-29	27.926 mi
Registration #3	2010-01-25	37.197 mi
Registration #4	2011-01-21	44.757 mi
Registration #5	2012-01-26	53.397 mi
Registration #6	2013-01-25	60.213 mi
Registration #7	2014-01-16	67.694 mi
Registration #8	2015-01-22	73.619 mi
Registration #9	2016-01-28	78.791 mi
Registration #10	2016-02-01	78.807 mi
Registration #11	2017-02-02	84.705 mi
Registration #12	2018-02-02	91.277 mi
Registration #13	2019-02-02	98.277 mi
Registration #14	2020-02-02	105.277 mi
Registration #15	2021-02-02	112.277 mi
Registration #16	2022-02-02	119.277 mi
Registration #17	2023-02-02	126.277 mi
Registration #18	2024-02-02	133.277 mi
Registration #19	2024-02-02	133.277 mi
Registration #20	2024-02-02	133.277 mi
Registration #21	2024-02-02	133.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Max. allowed weight	1565 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	1ZZ2365240