



PEUGEOT




report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 CC ACTIVE
Colour	Silver
Year of manufacture	2012
Top speed	119 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 2

Date 2021-09-04

Pictures 11

Listing price [View report](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date 2021-09-02

Pictures 2

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-15
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	21
Total items failed	11

MOT #12 2023-08-16 08:37

MOT test number 459610654471

Result ✓ Passed

Next expiry date 2024-08-15

Advice Nearside panel damaged

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11 2022-07-09 16:15

MOT test number 189539977228

Result ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #10 2021-07-06 14:26

MOT test number 381415316064

Result ✓ Passed

**MOT #9** 2021-06-22 11:40**MOT test number** 724986934374**Result** ✗ Failed**Fail** Offside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))**Fail** Offside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))**Fail** Nearside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))**Advice** Front Exhaust mounting defective (6.1.2 (a))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #8** 2019-10-04 08:29**MOT test number** 131136554751**Result** ✓ Passed**Advice** Front exhaust bracket corroded**MOT #7** 2019-10-03 10:21**MOT test number** 972314391476**Result** ✗ Failed**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Front exhaust bracket corroded**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #6** 2018-10-05 08:57**MOT test number** 290705943706**Result** ✓ Passed**Advice** Central Front Exhaust has a minor leak of exhaust gases flex pipe (6.1.2 (a))

**MOT #5** 2018-10-05 08:57**MOT test number** 291631036757**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Central Front Exhaust has a minor leak of exhaust gases flex pipe (6.1.2 (a))**Pass with rectification** Central Front Bumper likely to become detached (6.1.4 (a) (ii))**MOT #4** 2017-10-06 08:52**MOT test number** 456292843683**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases downpipe flexi (7.1.2)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened inside edge (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened inside edge (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened inside edge (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened inside edge (3.5.1i)**Advice** Rear both brakes binding slightly**MOT #3** 2016-10-03 11:53**MOT test number** 120117101549**Result** ✓ Passed**MOT #2** 2015-09-25 09:57**MOT test number** 323912165086**Result** ✓ Passed



MOT #12015-09-24 11:16

MOT test number854024876879

ResultX Failed

Fail

Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail

Exhaust system not adequately supported (7.1.1)

Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Nearside Rear brake disc modified but not seriously weakened (3.5.1n)

Advice

Nearside Rear Rear reflector slightly damaged but function not impaired (1.5.1c)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
15 August 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-10-05
Last registration	2023-08-16
Complete history	See info



Registration #1	2012-10-05	27 mi
Registration #2	2015-09-24	26.490 mi
Registration #3	2015-09-25	26.495 mi
Registration #4	2016-10-03	31.997 mi
Registration #5	2017-10-06	38.173 mi
Registration #6	2018-10-05	43.472 mi
Registration #7	2018-10-05	43.472 mi
Registration #8	2019-10-03	48.117 mi
Registration #9	2019-10-03	48.117 mi
Registration #10	2019-10-03	48.117 mi
Registration #11	2019-10-03	48.117 mi
Registration #12	2019-10-03	48.117 mi
Registration #13	2019-10-03	48.117 mi
Registration #14	2019-10-03	48.117 mi
Registration #15	2019-10-03	48.117 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	


View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1972 mm
Height	1387 mm
Length	4037 mm
Wheel base	2540 mm
Kerb weight	1428 kg
Max. allowed weight	1709 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	FHCA1551127