



LICHJ


report date: 2024-03-29

General information

Make	JAGUAR
Model	XJ V6 SPORT
Colour	Grey
Year of manufacture	2006
Top speed	144 mph
0 - 60 mph	6.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	231 BHP
Max. torque	284 Nm at 3.000 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.0 mpg
Consumption extra urban	36.2 mpg
Consumption combined	27.4 mpg
CO2 emission	249 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-10-18
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-01
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	20
Total items failed	1

MOT #18	2023-07-24 15:36
MOT test number	608175777091
Result	✓ Passed
Next expiry date	2024-08-01

MOT #17	2023-07-24 09:14
MOT test number	219506501942
Result	✗ Failed
MAJOR Offside Rear Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))	
MAJOR Offside Rear Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))	

MOT #16	2022-07-28 10:24
MOT test number	190130277446
Result	✓ Passed

MOT #15	2021-08-02 14:42
MOT test number	962919396190
Result	✓ Passed

**MOT #14** 2021-07-22 09:25**MOT test number** 953397637684**Result** ✗ Failed**MAJOR** Nearside Rear Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Front Lower Shock absorbers has a slightly worn bush (5.3.2 (c))**MAJOR** Offside Rear Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #13** 2020-10-21 09:27**MOT test number** 790101619277**Result** ✓ Passed**MOT #12** 2019-04-17 09:19**MOT test number** 886619942140**Result** ✓ Passed**MOT #11** 2018-04-27 10:22**MOT test number** 741137800937**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin both sides (3.5.1g)**Advice** Rear Tyre worn close to the legal limit both rear tyres (4.1.E.1)**MOT #10** 2017-04-25 07:40**MOT test number** 970934747426**Result** ✓ Passed

**MOT #9** 2016-10-12 11:14**MOT test number** 342043075657**Result** ✓ Passed**MOT #8** 2016-01-12 11:02**MOT test number** 759620112036**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front tyre side wall damaged**MOT #7** 2015-01-19 12:51**MOT test number** 218729915013**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #6** 2014-03-18 17:03**MOT test number** 219197974063**Result** ✓ Passed**Notice** Offside front tyre cracking**Notice** Nearside front tyre sidewall damaged should be replaced**MOT #5** 2013-03-21 12:02**MOT test number** 258200483051**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #4	2012-01-10 17:07
MOT test number	219940412004
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3	2011-01-08 09:26
MOT test number	109328401084
Result	✓ Passed

MOT #2	2009-08-18 16:42
MOT test number	692800539246
Result	✓ Passed

MOT #1	2009-08-18 12:35
MOT test number	531560639273
Result	✗ Failed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
1 August 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	1 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-07-31
Last registration	2023-07-24
Complete history	See info



Registration #1	2006-07-31	22 mi
Registration #2	2009-08-18	24.998 mi
Registration #3	2009-08-18	24.998 mi
Registration #4	2011-01-08	30.645 mi
Registration #5	2012-01-10	35.108 mi
Registration #6	2013-03-21	41.767 mi
Registration #7	2014-03-18	47.545 mi
Registration #8	2015-01-19	53.831 mi
Registration #9	2016-01-12	58.600 mi
Registration #10	2016-10-12	62.077 mi
Registration #11	2016-10-12	62.077 mi
Registration #12	2016-10-12	62.077 mi
Registration #13	2016-10-12	62.077 mi
Registration #14	2016-10-12	62.077 mi
Registration #15	2016-10-12	62.077 mi
Registration #16	2016-10-12	62.077 mi
Registration #17	2016-10-12	62.077 mi
Registration #18	2016-10-12	62.077 mi
Registration #19	2016-10-12	62.077 mi
Registration #20	2016-10-12	62.077 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Kerb weight	1605 kg
Max. allowed weight	2105 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	536960409WB