



report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO 16V SX MULTIJET
Colour	White
Year of manufacture	2016
Top speed	98 mph
0 - 60 mph	5.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.6 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-10-06
Pictures	15
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-18
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	5
Total items failed	4

MOT #7	2023-10-19 16:06
MOT test number	800659248615
Result	✓ Passed
Next expiry date	2024-10-18

MOT #6	2023-10-19 13:13
MOT test number	837887133484
Result	✗ Failed
<div><div>Advice</div> Offside Front Shock absorbers has light misting of oil (5.3.2 (b))</div> <div><div>Fail</div> Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))</div> <div><div>Fail</div> Offside Front Coil spring fractured or broken (5.3.1 (b) (i))</div> <div><div>Fail</div> Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))</div>	

MOT #5	2022-09-24 10:04
MOT test number	955222407813
Result	✓ Passed

MOT #4	2021-10-11 08:00
MOT test number	104459854426
Result	✓ Passed

**MOT #3** 2020-11-26 15:07**MOT test number** 109210997101**Result** ✓ Passed

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both front lower arm back bushes (5.3.4 (a) (i))

MOT #2 2020-11-16 14:20**MOT test number** 683743969667**Result** ✗ Failed

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure inner sidewall (5.2.3 (d) (ii))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both front lower arm back bushes (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge tyre is badly worn on inner edge to the point of nearly showing cords (5.2.3 (e))

MOT #1 2019-11-22 10:49**MOT test number** 889762519698**Result** ✓ Passed

Minor Central Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
18 October 2024

Tax status		Valid until 1 October
Days left		155
MOT expiry date		18 October 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-11-30
Last registration	2023-10-19
Complete history	See info



Registration #1	2016-11-30	26 mi
Registration #2	2019-11-22	53.954 mi
Registration #3	2020-11-16	63.596 mi
Registration #4	2020-11-26	63.596 mi
Registration #5	2023-10-19	63.596 mi
Registration #6	2023-10-19	63.596 mi
Registration #7	2023-10-19	63.596 mi
Registration #8	2023-10-19	63.596 mi
Registration #9	2023-10-19	63.596 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1832 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1345 kg
Max. allowed weight	2070 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	5640817