



report date: 2024-03-28

General information

| | |
|---------------------|---------------------------|
| Make | FORD |
| Model | FOCUS TITANIUM X TDCI 140 |
| Colour | Silver |
| Year of manufacture | 2009 |
| Top speed | 130 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 140 BHP |
| Max. torque | 320 Nm at 1.750 rpm |
| Engine capacity | 1.997 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.2 mpg |
| Consumption extra urban | 57.7 mpg |
| Consumption combined | 47.9 mpg |
| CO2 emission | 156 g/km |
| CO2 label | G |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-07-29 |
| Pictures | 7 |
| Listing price | View report |



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-30 |
| Pictures | 2 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2023-09-30 |
| MOT pass rate | 73 % |
| MOT passed | 11 |
| Failed MOT tests | 4 |
| Total advice items | 16 |
| Total items failed | 8 |

| | |
|------------------|---|
| MOT #15 | 2022-09-16 16:27 |
| MOT test number | 198446871262 |
| Result | ✓ Passed |
| Next expiry date | 2023-09-30 |
| Advice | Rear Tyres have splits on inner sidewalls |
| Advice | Nearside Rear Tyre on limit of 1.6mm |

| | |
|-----------------|------------------|
| MOT #14 | 2021-10-01 07:00 |
| MOT test number | 960780932659 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #13 | 2020-11-27 18:41 |
| MOT test number | 409567074585 |
| Result | ✓ Passed |

| | |
|-----------------|--|
| MOT #12 | 2020-11-24 18:00 |
| MOT test number | 730839467724 |
| Result | ✗ Failed |
| Fail | Offside Rear Position lamp not working (4.2.1 (a) (ii)) |
| Fail | Offside Front Position lamp not working (4.2.1 (a) (ii)) |
| Fail | Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) |

**MOT #11** 2019-06-19 11:15**MOT test number** 681541501966**Result** ✓ Passed**MOT #10** 2019-06-19 08:32**MOT test number** 732727063560**Result** ✗ Failed**Fail** Nearside Front Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #9** 2018-06-19 11:52**MOT test number** 555896618580**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8** 2017-06-14 12:55**MOT test number** 985643773776**Result** ✓ Passed**MOT #7** 2017-06-14 12:55**MOT test number** 228409361229**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)

**MOT #6** 2016-06-01 14:10**MOT test number** 620365046787**Result** ✓ Passed

- Advice** Nail in nearside rear
- Advice** Front tyres feathering on edges
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #5 2015-06-01 13:16**MOT test number** 898042455113**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components
- Notice** Screw in nearside rear tyre

MOT #4 2014-06-25 11:09**MOT test number** 835446874117**Result** ✓ Passed**MOT #3** 2013-06-27 11:34**MOT test number** 265488373484**Result** ✓ Passed**MOT #2** 2013-06-27 11:34**MOT test number** 159488573149**Result** ✗ Failed

- Pass with rectification** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Pass with rectification** Offside Front Tyre has ply or cords exposed (4.1.D.1b)



| | |
|-----------------|---|
| MOT #1 | 2012-06-13 12:32 |
| MOT test number | 269965662465 |
| Result | ✓ Passed |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-09-29 |
| Current registration | ***** |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2009-06-19 |
| Last registration | 2022-09-16 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2009-06-19 | 10 mi |
| Registration #2 | 2012-06-13 | 13.600 mi |
| Registration #3 | 2013-06-27 | 16.569 mi |
| Registration #4 | 2014-06-25 | 21.313 mi |
| Registration #5 | 2015-06-01 | 26.993 mi |
| Registration #6 | 2016-06-01 | 33.031 mi |
| Registration #7 | 2017-06-14 | 39.345 mi |
| Registration #8 | 2017-06-14 | 39.345 mi |
| Registration #9 | 2018-06-19 | 44.880 mi |
| Registration #10 | 2019-06-01 | 50.317 mi |
| Registration #11 | 2019-06-01 | 50.317 mi |
| Registration #12 | 2019-06-01 | 50.317 mi |
| Registration #13 | 2019-06-01 | 50.317 mi |
| Registration #14 | 2019-06-01 | 50.317 mi |
| Registration #15 | 2019-06-01 | 50.317 mi |
| Registration #16 | 2019-06-01 | 50.317 mi |
| Registration #17 | 2019-06-01 | 50.317 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2078 mm |
| Height | 1451 mm |
| Length | 4778 mm |
| Wheel base | 2754 mm |
| Max. allowed weight | 2170 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |

Engine number

9B03425