



AK06LLE

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Blue
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	169 Nm at 2.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.5 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-26
Pictures	35
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #18	2021-12-17 07:40
MOT test number	745712107312
Result	✓ Passed
Next expiry date	2022-12-16
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Inner Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #17	2021-12-11 11:57
MOT test number	381493838629
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
MAJOR	Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
DANGEROUS	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Front Inner Track rod end ball joint has slight play (2.1.3 (b) (i))
MAJOR	Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))



MOT #16

2020-12-15 10:18

MOT test number

980122113591

Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 1.6mm (5.2.3 (e))	
Advice	Nearside Play in steering rack inner joint(s)	
Advice	Steering rack has slight free play detected at steering wheel (2.3 (a) (i))	
Advice	Rear Brake pad(s) wearing thin all (1.1.13 (a) (ii))	
Advice	Oil leak, but not excessive engine / gearbox (8.4.1 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge badly worn on inner shoulder but cords not visible at time of test (5.2.3 (e))	
Advice	Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement top mount (5.3.4 (a) (i))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))	

**MOT #15**

2020-12-14 09:39

MOT test number

338139942347

Result**✗ Failed**

- MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 1.6mm (5.2.3 (e))
- MAJOR** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Play in steering rack inner joint(s)
- MAJOR** Offside Rear Brake lever has abnormal movement of levers indicating excessive wear or maladjustment (1.1.15 (f))
- Advice** Oil leak, but not excessive engine / gearbox (8.4.1 (a) (i))
- Advice** Rear Brake pad(s) wearing thin all (1.1.13 (a) (ii))
- Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement top mount (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge badly worn on inner shoulder but cords not visible at time of test (5.2.3 (e))
- MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #14**

2019-06-24 08:40

MOT test number

749868141530

Result

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement top mount (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement top mount (5.3.4 (a) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)

MOT #13

2019-06-24 08:40

MOT test number

379304200839

Result

✗ Failed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement top mount (5.3.4 (a) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement top mount (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #12

2018-06-01 15:23

MOT test number

807238015051

Result

✓ Passed

**MOT #11** 2018-06-01 11:06**MOT test number** 170708971923**Result** ✗ Failed**MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Nearside Headlamp aim not tested (4.1.2 (b))**MOT #10** 2017-06-16 15:33**MOT test number** 490867774949**Result** ✓ Passed**MOT #9** 2016-06-14 16:25**MOT test number** 816424711411**Result** ✓ Passed**MOT #8** 2015-06-11 08:44**MOT test number** 497642665126**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2014-06-13 11:54**MOT test number** 368084964123**Result** ✓ Passed**MOT #6** 2013-06-20 14:08**MOT test number** 606121073132**Result** ✓ Passed



MOT #5	2012-04-25 10:56
---------------	------------------

MOT test number	798186612118
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2011-03-29 16:42
---------------	------------------

MOT test number	207748481003
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Oil leak
---------------	----------

MOT #3	2010-03-29 13:45
---------------	------------------

MOT test number	611478580099
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2010-03-29 13:10
---------------	------------------

MOT test number	894268580093
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Offside Front Headlamp aim too high (1.8)
-------------	---

Fail	Nearside Front Headlamp aim too high (1.8)
-------------	--

MOT #1	2009-04-07 16:49
---------------	------------------

MOT test number	451417099008
------------------------	--------------

Result	✓ Passed
---------------	----------



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-04-10
Last registration	2021-12-17
Complete history	See info



Registration #1	2006-04-10	10 mi
Registration #2	2009-04-07	32.304 mi
Registration #3	2010-03-29	41.654 mi
Registration #4	2010-03-29	41.654 mi
Registration #5	2011-03-29	53.763 mi
Registration #6	2012-04-25	54.068 mi
Registration #7	2013-06-20	60.189 mi
Registration #8	2014-06-13	67.641 mi
Registration #9	2015-06-11	75.303 mi
Registration #10	2016-06-14	84.854 mi
Registration #11	2016-06-14	84.854 mi
Registration #12	2016-06-14	84.854 mi
Registration #13	2016-06-14	84.854 mi
Registration #14	2016-06-14	84.854 mi
Registration #15	2016-06-14	84.854 mi
Registration #16	2016-06-14	84.854 mi
Registration #17	2016-06-14	84.854 mi
Registration #18	2016-06-14	84.854 mi
Registration #19	2016-06-14	84.854 mi
Registration #20	2016-06-14	84.854 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1836 mm
Height	1498 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1342 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	AZJ 739995