




report date: 2024-03-28

General information

Make	FORD
Model	B-MAX ZETEC
Colour	Blue
Year of manufacture	2014
Top speed	109 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 kW / 101 HP / 99 BHP
Max. torque	170 Nm at 1.400 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 3

Date	2023-10-01
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 2


Date	2021-07-12
Pictures	10
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-01-30
Pictures	23
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-06-30
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	31
Total items failed	5

MOT #11 2023-06-23 09:08

MOT test number 367102688197

Result ✔ Passed

Next expiry date 2024-06-30

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 195/60R15 88V (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10 2022-06-28 09:31

MOT test number 149108289729

Result ✔ Passed

- Advice** Rear Tyre slightly damaged/cracking or perishing Both heavily perished 195/60/15 (5.2.3 (d) (ii))



MOT #9 2021-07-01 16:08

MOT test number 315209560151

Result ✔ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear possible puncture

MOT #8 2021-06-29 12:26

MOT test number 553255466919

Result ✘ Failed

- Advice** Offside Rear possible puncture
- Fail** Offside Front Seat belt webbing significantly weakened seat belt frayed (7.1.2 (b) (ii))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2020-08-01 08:00

MOT test number 522004349087

Result ✔ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #6	2019-07-10 15:52
MOT test number	980804766677
Result	✓ Passed
Advice	Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Offside Front Tyre slightly damaged (5.2.3 (d) (ii))
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Both front tyres cracking
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #5	2018-07-10 15:51
MOT test number	719762827265
Result	✓ Passed

MOT #4	2018-07-10 09:19
MOT test number	872562701202
Result	✗ Failed
Fail	Nearside Front Side repeater not working (4.4.1 (a) (ii))

MOT #3	2017-08-10 09:07
MOT test number	612121629853
Result	✓ Passed



MOT #2 2017-01-30 09:21

MOT test number 159632792611

Result ✔ Passed

- Advice** Tyre sealant been used
- Advice** Cut nearside front tyre wall and tread wearing on edges
- Advice** Cut nearside rear tyre wall
- Advice** Offside front tyre tread wearing on edges
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #1 2017-01-30 09:21

MOT test number 261784108135

Result ✘ Failed

- Advice** Cut nearside front tyre wall and tread wearing on edges
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Cut nearside rear tyre wall
- Advice** Offside front tyre tread wearing on edges
- Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)
- Advice** Tyre sealant been used



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
30 June 2024

Tax status Valid until 1 January

Days left 247

MOT expiry date 30 June 2024

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-




Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YX14
Plate since	2019-03-28
Current registration	YX14
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-03-31
Last registration	2023-06-23
Complete history	See info



Registration #1	2014-03-31	22 mi
Registration #2	2017-01-30	22.412 mi
Registration #3	2017-01-30	22.412 mi
Registration #4	2017-08-10	23.925 mi
Registration #5	2018-07-10	27.694 mi
Registration #6	2018-07-10	27.694 mi
Registration #7	2019-07-10	31.385 mi
Registration #8	2020-08-01	38.031 mi
Registration #9	2020-08-01	38.031 mi
Registration #10	2020-08-01	38.031 mi
Registration #11	2020-08-01	38.031 mi
Registration #12	2020-08-01	38.031 mi
Registration #13	2020-08-01	38.031 mi
Registration #14	2020-08-01	38.031 mi
Registration #15	2020-08-01	38.031 mi

[More info >](#)



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1760 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	ES23713