



report date: 2024-03-28

General information

Make	CITROEN
Model	DS4 HDI DSTYLE
Colour	Bronze
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	122 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-23
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	27
Total items failed	15

MOT #14	2024-02-23 10:47
MOT test number	895500336728
Result	✓ Passed
Next expiry date	2025-02-23

MOT #13	2023-02-24 16:51
MOT test number	667184634315
Result	✓ Passed

MOT #12	2022-02-24 15:15
MOT test number	777071654512
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside front bumper damaged
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2022-02-24 11:53

MOT test number

456747714926

Result**✗ Failed****Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Headlamp light source and lamp not compatible (4.1.4 (c))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Headlamp light source and lamp not compatible (4.1.4 (c))**Fail** Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside front bumper damaged**Fail** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))**MOT #10**

2021-02-03 13:56

MOT test number

270117179236

Result**✓ Passed****MOT #9**

2021-02-02 11:43

MOT test number

965054563636

Result**✗ Failed****Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8**

2019-10-29 10:09

MOT test number

566405470526

Result**✓ Passed**



MOT #7	2019-10-29 10:09
MOT test number	274138600368
Result	✗ Failed
<div>Pass with rectification</div> Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	

MOT #6	2018-04-06 07:46
MOT test number	947930536370
Result	✓ Passed
<div>Advice</div> Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)	
<div>Advice</div> Items removed from driver's view prior to test	
<div>Advice</div> Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)	
<div>Advice</div> Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
<div>Advice</div> Parking brake lever has little reserve travel (3.1.6b)	

**MOT #5**

2018-04-04 10:37

MOT test number

776570506382

Result**✗ Failed**

- Advice** Items removed from driver's view prior to test
- Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Offside Rear rear brake binding (3.7.B.1)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Fail** Nearside Front Headlamp not working on main beam (1.7.5a)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Nearside Rear rear brake binding (3.7.B.1)
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Front Headlamp not working on main beam (1.7.5a)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #4

2017-03-06 13:02

MOT test number

912305774882

Result**✓ Passed**

**MOT #3** 2016-10-22 14:42**MOT test number** 354146416336**Result** ✓ Passed

- Advice** Nearside Front fog lamp broken
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front drivers window out of runner
- Advice** Oil leak major leak
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2015-11-06 12:11**MOT test number** 267850022989**Result** ✓ Passed**MOT #1** 2014-11-11 15:33**MOT test number** 818535214382**Result** ✓ Passed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Items removed from driver's view prior to test



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
23 February 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	23 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-11-08
Last registration	2024-02-23
Complete history	See info



Registration #1	2011-11-08	15 mi
Registration #2	2014-11-11	35.380 mi
Registration #3	2015-11-06	55.127 mi
Registration #4	2016-10-22	72.789 mi
Registration #5	2017-03-06	75.389 mi
Registration #6	2018-04-04	84.070 mi
Registration #7	2018-04-06	84.070 mi
Registration #8	2019-10-29	94.026 mi
Registration #9	2020-05-20	95.377 mi
Registration #10	2021-05-20	95.377 mi
Registration #11	2022-05-20	95.377 mi
Registration #12	2023-05-20	95.377 mi
Registration #13	2024-05-20	95.377 mi
Registration #14	2025-05-20	95.377 mi
Registration #15	2026-05-20	95.377 mi
Registration #16	2027-05-20	95.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1523 mm
Length	4275 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBET3005152